

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|---------------|-----------------|-----------|--------------|
| AN1311 | NJM311D | | PANASONIC |
| AN1311S | NJM311M | Note 4 | PANASONIC |
| AN1319 | NJM319D | | PANASONIC |
| AN1319S | NJM319M | Note 4 | PANASONIC |
| AN1339 | NJM2901N | | PANASONIC |
| AN1339NS | NJM2901M | Note 4 | PANASONIC |
| AN1393 | NJM2903D | | PANASONIC |
| AN1393NS | NJM2903M | Note 4 | PANASONIC |
| AN311 | NJM311D | | PANASONIC |
| AN311S | NJM311M | Note 4 | PANASONIC |
| AN7810 TO-220 | NJM7810FA | Note 2 | PANASONIC |
| AN78L06 | NJM78L06A | | PANASONIC |
| AN78L08 | NJM78L08A | | PANASONIC |
| AN78L09 | NJM78L09A | | PANASONIC |
| AN78L18 | NJM78L18A | | PANASONIC |
| AN78L20 | NJM78L20A | | PANASONIC |
| AN78L24 | NJM78L24A | | PANASONIC |
| AN78M10 | NJM78M10FA | Note 2 | PANASONIC |
| AN78M18 | NJM78M18FA | Note 2 | PANASONIC |
| AN78M20 | NJM78M20FA | Note 2 | PANASONIC |
| AN7924 | NJM7924FA | Note 2 | PANASONIC |
| AN79L05 | NJM79L05A | | PANASONIC |
| AN79L06 | NJM79L06A | | PANASONIC |
| AN79L08 | NJM79L08A | | PANASONIC |
| AN79L09 | NJM79L09A | | PANASONIC |
| AN79L12 | NJM79L12A | | PANASONIC |
| AN79L15 | NJM79L15A | | PANASONIC |
| AN79L18 | NJM79L18A | | PANASONIC |
| AN79L24 | NJM79L24A | | PANASONIC |
| AN8388 | NJW4301 | Note 4 | PANASONIC |
| BA1404 | NJM2035 | Note 4 | ROHM |
| BA15532 | NJM5532D | | ROHM |
| BA15532 | NJM5532M | Note 1 | ROHM |
| BA15534 | NJM5534D | | ROHM |
| BA15534 | NJM5534M | Note 1 | ROHM |
| BA3404F | NJM2076M | Note 1 | ROHM |
| BA3880 | NJM2150/A | Note 4, 6 | ROHM |
| BA3880 | NJM2152 | Note 4, 6 | ROHM |
| BA4558 | NJM4558D | | ROHM |
| BA4558S | NJM4558E | | ROHM |
| BA4558S | NJM4558M | Note 1 | ROHM |
| BA4560 | NJM4560D | | ROHM |
| BA4560F | NJM4560E | | ROHM |
| BA4560F | NJM4560M | Note 1 | ROHM |
| BA6295 | NJW4301 | Note 4 | ROHM |
| BA6296/97/98 | NJW4301 | Note 4 | ROHM |
| BA7001 | NJM2233 | | ROHM |
| BA7001 | NJM2533 | | ROHM |
| BA7021 | NJM2273S | | ROHM |
| BA7021 | NJM2273 | | ROHM |
| BA7602 | NJM2283D | | ROHM |
| BA7602 | NJM2283 | | ROHM |
| BA7602F | NJM2283M | Note 1 | ROHM |
| BA7603 | NJM2286D | | ROHM |
| BA7603 | NJM2286 | | ROHM |
| BA7603F | NJM2286M | Note 1 | ROHM |
| BA7607 | NJM2285D | | ROHM |
| BA7607 | NJM2285 | | ROHM |
| BA7607F | NJM2285M | Note 1 | ROHM |
| BA7609 | NJM2284D | | ROHM |
| BA7609 | NJM2284 | | ROHM |
| BA7609F | NJM2284M | Note 1 | ROHM |
| BA7611 | NJM2245 | Note 1 | ROHM |
| BA7611 | NJM2246 | | ROHM |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|---------------|-----------------|-----------|-----------------|
| BA7611AN | NJM2246L | | ROHM |
| BA7677 | NJM2151 | Note 4, 6 | ROHM |
| BA7677 | NJM2151A | | ROHM |
| BH3541 | NJM2768 | | ROHM |
| BH3543 | NJM2769A | | ROHM |
| BH3868 | NJW1130 | Note 4, 6 | ROHM |
| BH3868 | NJM2155 | | ROHM |
| BU2029/4X | NJU3713 | | ROHM |
| BU2114 | NJU3711 | | ROHM |
| CA555 DIP | NJM555D | | HARRIS |
| CA555 SMT | NJM555E | | HARRIS |
| CA555 SMT | NJM555M | Note 1 | HARRIS |
| CA556 DIP | NJM556D | | HARRIS |
| CA556 SMT | NJM556M | Note 1 | HARRIS |
| CA723 DIP | NJM723D | | HARRIS |
| CA723 SMT | NJM723M | Note 1 | HARRIS |
| CD4051BC | NJU4051BD | | NATIONAL |
| CD4051BE | NJU4051BD | | HARRIS |
| CD4051BM | NJU4051BM | Note 1 | NATIONAL |
| CD4052BC | NJU4052BD | | NATIONAL |
| CD4052BE | NJU4052BD | | HARRIS |
| CD4052BM | NJU4052BM | Note 1 | NATIONAL |
| CD4053BC | NJU4053BD | | NATIONAL |
| CD4053BE | NJU4053BD | | HARRIS |
| CD4053BM | NJU4053BM | Note 1 | NATIONAL |
| CD4066BC | NJU4066BD | | NATIONAL |
| CD4066BE | NJU4066BD | | HARRIS |
| CD4066BM | NJU4066BM | Note 1 | NATIONAL |
| CF5002 series | NJU6395 series | | NPC |
| CF5005 | NJU6393 | | NPC |
| CG1022TM | NJG1508/09 | SIMILAR | SONY |
| CGX1030N | NJG1309 | SIMILAR | SONY |
| CNB1001 | NJL5183K/97K | | MATSUSHITA |
| CNB2001 | NJL5194K | | MATSUSHITA |
| CS54924 | NJU25301 | Note 4, 6 | CRYSTAL |
| CXA1103 | NJM2232A | | SONY |
| CXA1183 | NJM2292 | Note 4 | SONY |
| CXA1474 | NJM2294 | Note 4 | SONY |
| CXA1558L | NJM2279 | Note 4 | SONY |
| CXA1571 | NJM2117 | | SONY |
| CXG1006N/16N | NJG1506/07 | Note 4 | SONY |
| CXG1009TN | NJG1505/12 | | SONY |
| CXG1010N | NJG1301/02 | Note 4 | SONY |
| CXG1013N/14N | NJG1705/09 | Note 4 | SONY |
| CXG1013N/14N | NJG1705/09 | | SONY |
| CXG1022TM | NJG1508/09 | Note 4 | SONY |
| CXG1030N | NJG1309 | Note 4 | SONY |
| CXG1040TN | NJG1524 | | SONY |
| CXG1064A | NJG1515A | Note 4 | SONY |
| CXG1064ATN | NJG1515A | | SONY |
| CXG1068N | NJG1519 | Note 4 | SONY |
| CXG1077TN | NJG1516 | Note 4 | SONY |
| CXM-134L | NJL81H SERIES | | SONY |
| CXM-134S | NJL81V SERIES | | SONY |
| DAC-0801LCM | NJMDAC-08MC | Note 1 | NATIONAL |
| DAC-0801LCN | NJMDAC-08DE | | NATIONAL |
| DAC08CD | NJMDAC-08MC | Note 1 | MOTOROLA |
| DAC08CP | NJMDAC-08DE | | MOTOROLA |
| DAC-08N | NJMDAC-08DE | | RAYTHEON |
| DG201A DIP | NJU201AD | | HARRIS |
| DG201A DIP | NJU201AD | | SILICONIX/TEMIC |
| DG201A DIP | NJU7301D | | HARRIS |
| DG201A DIP | NJU7301D | | SILICONIX/TEMIC |
| DG201A SMT | NJU201AM | Note 1 | HARRIS |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|------------------|-----------------|-----------|-----------------|
| DG201A SMT | NJU201AM | Note 1 | SILICONIX/TEMIC |
| DG201A SMT | NJU7301M | Note 1 | HARRIS |
| DG201A SMT | NJU7301M | Note 1 | SILICONIX/TEMIC |
| DG211 DIP | NJU211D | | HARRIS |
| DG211 DIP | NJU211D | | SILICONIX/TEMIC |
| DG211 SMT | NJU211M | Note 1 | HARRIS |
| DG211 SMT | NJU211M | Note 1 | SILICONIX/TEMIC |
| DS14C232 | NJU6401B | Note 4 | NATIONAL |
| DS14C232 | NJU6402B | Note 4 | NATIONAL |
| DSP56011 | NJU25301 | Note 4, 6 | MOTOROLA |
| FA7610P/N | NJM2368 | | FUJI ELECTRIC |
| FC2245 | NJU6468 | | OTHERS |
| FC2326K | NJU6469/6461 | | OTHER |
| FCS2331K | NJU6676 | | OTHER |
| GN01046B | NJG1705/09 | Note 4 | PANASONIC |
| GN01071B | NJG1104 | Note 4 | PANASONIC |
| GN01087B | NJG1705/09 | | PANASONIC |
| GN01096B | NJG1104 | | PANASONIC |
| GN02018B/19B | NJG1550/51 | Note 4 | PANASONIC |
| GN02018B/19B | NJG1552/53 | Note 4 | PANASONIC |
| GN02022B | NJG1550/51 | | PANASONIC |
| GN02032B | NJG1555 | | PANASONIC |
| GN02035B | NJG1557 | Note 4 | PANASONIC |
| GN05002 | NJG1309 | Note 4 | PANASONIC |
| GN4002 | NJG1508/09 | Note 4 | PANASONIC |
| GN4005 | NJG1506/07 | Note 4 | PANASONIC |
| GP1U10X | NJL61H SERIES | | SHARP |
| GP1U26X/R | NJL82H SERIES | | SHARP |
| GP1U27R | NJL67H SERIES | | SHARP |
| GP1U27X | NJL63H SERIES | | SHARP |
| GP1U28Q | NJL65V SERIES | | SHARP |
| GP1U28R | NJL68H SERIES | | SHARP |
| GP1U28X | NJL64H SERIES | | SHARP |
| GP1U28Y | NJL62V SERIES | | SHARP |
| GP1U59X | NJL81H SERIES | | SHARP |
| GP1U901X | NJL62H SERIES | | SHARP |
| GP2L09 | NJL5166K | | SHARP |
| GP2L24 | NJL5168K | | SHARP |
| GP2L26 | NJL5164K-F10 | | SHARP |
| GP2S09 | NJL5165K | | SHARP |
| GP2S24 | NJL5167K | | SHARP |
| GP2S26 | NJL5163K-F10 | | SHARP |
| GP2S26 | NJL5193K-F10 | | SHARP |
| GP2S27 | NJL5183K/97K | | SHARP |
| GP2S40 | NJL5165K | | SHARP |
| HA12163 | NJM2085 | Note 4 | HITACHI |
| HA16128L | NJU7092 | Note 4 | HITACHI |
| HA16128L | NJU7092F | | HITACHI |
| HA17339P | NJM2901N | | HITACHI |
| HA17393FP | NJM2903M | Note 4 | HITACHI |
| HA17393PS | NJM2903D | | HITACHI |
| HA17901P | NJM2901N | | HITACHI |
| HA17903FP | NJM2903M | Note 4 | HITACHI |
| HA17903PS | NJM2903D | | HITACHI |
| HA22033 | NJG1103 | | HITACHI |
| HD404201 | NJU3502 | | HITACHI |
| HD404344 | NJU3504 | | HITACHI |
| HD40L4201 | NJU3502 | | HITACHI |
| HD44100 | NJU6407C | Note 4 | HITACHI |
| HD44100 | NJU6407CR | Note 4 | HITACHI |
| HD44102 (50 OUT) | NJU6417C | Note 4 | HITACHI |
| HD44780 | NJU6408B | Note 4 | HITACHI |
| HD44780U | NJU6468 | | HITACHI |
| HD44780U | NJU6470 | | HITACHI |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------------|--------|--------------|
| HD66100 | NJU6415 | Note 4 | HITACHI |
| HD66100 | NJU6416 | Note 4 | HITACHI |
| HD66108 | NJU6575A | Note 4 | HITACHI |
| HD66108 | NJU6676 | Note 4 | HITACHI |
| HD66410 | NJU6455 | Note 4 | HITACHI |
| HD66410 | NJU6575A | | HITACHI |
| HD66700 | NJU6469 | | HITACHI |
| HD66705 | NJU6461 | | HITACHI |
| HD66710 | NJU6420B | Note 4 | HITACHI |
| HD66712 | NJU6406B | Note 4 | HITACHI |
| HD66712 | NJU6466/65/75/NJU6620 | | HITACHI |
| HD66717 | NJU6466/65/75/NJU6620 | | HITACHI |
| HD66720 | NJU6468 | | HITACHI |
| HD66724 | NJU6620 | Note 4 | HITACHI |
| HD66727 | NJU6475B | | HITACHI |
| HD66727 | NJU6466/65/75/NJU6620 | | HITACHI |
| HD66728 | NJU6678 | Note 4 | HITACHI |
| HD66750 | NJU6679 | | HITACHI |
| HD66750/1 | NJU6679 | Note 4 | HITACHI |
| HD66753 | NJU6682 | Note 4 | HITACHI |
| HD66780 | NJU6468 | Note 4 | HITACHI |
| HPMX3003 | NJG1701 | Note 4 | HP |
| HS0038A | NJL85V SERIES | | VISHAY |
| HS0038B | NJL81V SERIES | | VISHAY |
| HT44100 | NJU3503 | | HOLTEK |
| ICL7106 | NJU9201B/C | Note 4 | HARRIS |
| ICL7106 | NJU9201B/C | Note 4 | MAXIM |
| ICL7107 | NJU9202B | Note 4 | HARRIS |
| ICL7107 | NJU9202B | Note 4 | MAXIM |
| ICL7116 | NJU9203B | Note 4 | HARRIS |
| ICL7116 | NJU9203B | Note 4 | MAXIM |
| ICL7117 | NJU9204B | Note 4 | HARRIS |
| ICL7117 | NJU9204B | Note 4 | MAXIM |
| ICL7117 | NJU9214 | Note 4 | HARRIS |
| ICL7126 | NJU9201B/C | Note 4 | HARRIS |
| ICL7126 | NJU9201B/C | Note 4 | MAXIM |
| ICL7136 | NJU9201B/C | Note 4 | HARRIS |
| ICL7136 | NJU9201B/C | Note 4 | MAXIM |
| ICL7137 | NJU9202B | Note 4 | HARRIS |
| ICL7137 | NJU9202B | Note 4 | MAXIM |
| ICL7139 | NJU9207B | Note 4 | HARRIS |
| ICL7139 | NJU9207B | | MAXIM |
| ICL7139 | NJU9212 | Note 4 | HARRIS |
| ICL761AD | NJU7071M | Note 1 | HARRIS |
| ICL761AP | NJU7071D | | HARRIS |
| ICL761CD | NJU7031M | Note 1 | HARRIS |
| ICL761CP | NJU7031D | | HARRIS |
| ICL762AD | NJU7072M | Note 1 | HARRIS |
| ICL762AP | NJU7072D | | HARRIS |
| ICL762CD | NJU7032M | Note 1 | HARRIS |
| ICL762CP | NJU7032D | | HARRIS |
| ICL764AD | NJU7074M | Note 1 | HARRIS |
| ICL764AP | NJU7074D | | HARRIS |
| ICL764CD | NJU7034M | Note 1 | HARRIS |
| ICL764CP | NJU7034D | | HARRIS |
| ICL7660CBA | NJU7660M | Note 1 | HARRIS |
| ICL7660CBA | NJU7660M | Note 1 | MAXIM |
| ICL7660CPA | NJU7660D | | HARRIS |
| ICL7660CPA | NJU7660D | | MAXIM |
| ICL7660CSA | NJU7660M | Note 1 | HARRIS |
| ICL7660CSA | NJU7660M | Note 1 | MAXIM |
| ICL7662CBA | NJU7662M | Note 1 | HARRIS |
| ICL7662CBA | NJU7662M | Note 1 | MAXIM |
| ICL7662CPA | NJU7662D | | HARRIS |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|--------------|-----------------|--------|--------------|
| ICL7662CPA | NJU7662D | | MAXIM |
| ICL7662CSA | NJU7662M | Note 1 | HARRIS |
| ICL7662CSA | NJU7662M | Note 1 | MAXIM |
| ICL76L1AD | NJU7051M | Note 1 | HARRIS |
| ICL76L1AP | NJU7051D | | HARRIS |
| ICL76L1CD | NJU7001M | Note 1 | HARRIS |
| ICL76L1CP | NJU7001D | | HARRIS |
| ICL76L2AD | NJU7052M | Note 1 | HARRIS |
| ICL76L2AP | NJU7052D | | HARRIS |
| ICL76L2CD | NJU7002M | Note 1 | HARRIS |
| ICL76L2CP | NJU7002D | | HARRIS |
| ICL76L4AD | NJU7054M | Note 1 | HARRIS |
| ICL76L4AP | NJU7054D | | HARRIS |
| ICL76L4CD | NJU7004M | Note 1 | HARRIS |
| ICL76L4CP | NJU7004D | | HARRIS |
| ICL76M1AD | NJU7061M | Note 1 | HARRIS |
| ICL76M1AP | NJU7061D | | HARRIS |
| ICL76M1CD | NJU7021M | Note 1 | HARRIS |
| ICL76M1CP | NJU7021D | | HARRIS |
| ICL76M2AD | NJU7062M | Note 1 | HARRIS |
| ICL76M2AP | NJU7062D | | HARRIS |
| ICL76M2CD | NJU7022M | Note 1 | HARRIS |
| ICL76M2CP | NJU7022D | | HARRIS |
| ICL76M4AD | NJU7064M | Note 1 | HARRIS |
| ICL76M4AP | NJU7064D | | HARRIS |
| ICL76M4CD | NJU7024M | Note 1 | HARRIS |
| ICL76M4CP | NJU7024D | | HARRIS |
| IR3E05A | NJM2366 | Note 4 | SHARP |
| IR3M03A | NJM2360D | | SHARP |
| IR3M03AN | NJM2360M | Note 1 | SHARP |
| IR3P89/90 | NJW1300 | | SHARP |
| IR9022 | NJM022D | | SHARP |
| IR9022N | NJM022E | | SHARP |
| IR9022N | NJM9022M | Note 1 | SHARP |
| IR9431 | NJM431D | | SHARP |
| IR9431N | NJM431M | Note 1 | SHARP |
| IS1U60 | NJL61V SERIES | | SHARP |
| IS1U60L | NJL51H | | SHARP |
| IS1U60L | NJL51V | | SHARP |
| IS1U621L | NJL61H | | SHARP |
| IS1U621L | NJL81H SERIES | | SHARP |
| IS1U621L | NJL81V SERIES | | SHARP |
| ISU60L | NJL61H SERIES | | SHARP |
| KA33063A DIP | NJM2360AD | | SAMSUNG |
| KA33063A SMT | NJM2360AM | Note 1 | SAMSUNG |
| KAD7000 | NJU9207B | Note 4 | SAMSUNG |
| KAD7000 | NJU9212 | Note 4 | SAMSUNG |
| KAD7001 | NJU9210C | Note 4 | SAMSUNG |
| KS0032 | NJU6635 | | OTHER |
| KS0066U | NJU6468 | | OTHERS |
| KS0071B | NJU6406B | | SAMSUNG |
| KS0071B | NJU6428/29 | | SAMSUNG |
| KS0072 | NJU6460A | | OTHER |
| KS0713 | NJU6677 | | OTHER |
| KS51700 | NJU3501 | | SAMSUNG |
| KS57C0002 | NJU3504 | | SAMSUNG |
| KS57C0108 | NJU3505 | | SAMSUNG |
| KS57C0302 | NJU3504 | | SAMSUNG |
| KS57C04004 | NJU3504 | | SAMSUNG |
| KU163 | NJL5183K/97K | | STANLEY |
| L7805CV | NJM7805FA | Note 2 | ST MICRO |
| L7806CV | NJM7806FA | Note 2 | ST MICRO |
| L7808CV | NJM7808FA | Note 2 | ST MICRO |
| L7809CV | NJM7809FA | Note 2 | ST MICRO |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-----------------|--------------------|-----------|--------------|
| L7812CV | NJM7812FA | Note 2 | ST MICRO |
| L7815CV | NJM7815FA | Note 2 | ST MICRO |
| L7818CV | NJM7818FA | Note 2 | ST MICRO |
| L7820CV | NJM7820FA | Note 2 | ST MICRO |
| L7824CV | NJM7824FA | Note 2 | ST MICRO |
| L78L05CD | NJM78L05EA | | ST |
| L78LR05 | NJM78LR05 | | SANYO |
| L78LR05 | NJM78LR05 | Note 4 | SANYO |
| L78M05CV | NJM78M05FA | Note 2 | ST MICRO |
| L78M06CV | NJM78M05FA | Note 2 | ST MICRO |
| L78M06CV | NJM78M06FA | Note 2 | ST MICRO |
| L78M08CV | NJM78M08FA | Note 2 | ST MICRO |
| L78M10CV | NJM78M10FA | Note 2 | ST MICRO |
| L78M12CV | NJM78M12FA | Note 2 | ST MICRO |
| L78M15CV | NJM78M15FA | Note 2 | ST MICRO |
| L78M18CV | NJM78M18FA | Note 2 | ST MICRO |
| L78M20CV | NJM78M20FA | Note 2 | ST MICRO |
| L78M24CV | NJM78M24FA | Note 2 | ST MICRO |
| L7905CV | NJM7905FA | Note 2 | ST MICRO |
| L7906CV | NJM7906FA | Note 2 | ST MICRO |
| L7908CV | NJM7908FA | Note 2 | ST MICRO |
| L7912CV | NJM7912FA | Note 2 | ST MICRO |
| L7915CV | NJM7915FA | Note 2 | ST MICRO |
| L7918CV | NJM7918FA | Note 2 | ST MICRO |
| L7924CV | NJM7924FA | Note 2 | ST MICRO |
| LA2780 | NJM2177 | | SANYO |
| LA2780 & LV1010 | NJM2177 & NJU9702 | Note 4 | SANYO |
| LA2785 | NJW1102 | | SANYO |
| LA2785 | NJM2177A | | SANYO |
| LA2785 & LV1010 | NJM2177A & NJU9702 | Note 4 | SANYO |
| LA2785 & LV1010 | NJW1102 & NJU9702 | Note 4, 6 | SANYO |
| LA2785 & LV1010 | NJW1102A & NJU9702 | Note 4, 6 | SANYO |
| LA5315M | NJM2366 | Note 4 | SANYO |
| LA5316M | NJM2366 | Note 4 | SANYO |
| LA5317M | NJM2366 | Note 4 | SANYO |
| LA5318M | NJM2366 | Note 4 | SANYO |
| LA5431 | NJM431 | | SANYO |
| LA5524 | NJM2606 | | SANYO |
| LA5524 | NJM2606A | | SANYO |
| LA5524 | NJM2606/NJM2606A | | SANYO |
| LA6339D | NJM2901N | | SANYO |
| LA6339M | NJM2901M | Note 4 | SANYO |
| LA6393D | NJM2903D | | SANYO |
| LA6393M | NJM2903M | Note 4 | SANYO |
| LA6530 | NJW4301 | | SANYO |
| LA6530A | NJW4301 | Note 4 | SANYO |
| LA6531 | NJW4301 | Note 4 | SANYO |
| LA8608 | NJM2292 | Note 4 | SANYO |
| LA8615 | NJM2294 | Note 4 | SANYO |
| LB1821 | NJW4302 | | SANYO |
| LC6427N/F/L | NJU3502 | | SANYO |
| LC65102A | NJU3503 | | SANYO |
| LC65104A | NJU3504 | | SANYO |
| LC651102N/F/L | NJU3503 | | SANYO |
| LC651104N/F/L | NJU3504 | | SANYO |
| LC6528N/F/L | NJU3501 | | SANYO |
| LC6546N/F/L | NJU3502 | | SANYO |
| LC66404A | NJU3504 | | SANYO |
| LC66408A | NJU3502 | | SANYO |
| LC7522 | NJU7305 | Note 4 | SANYO |
| LC7523 | NJU7305 | Note 4 | SANYO |
| LC7582 | NJU6432BC | | SANYO |
| LC7582 | NJU6432BF | | SANYO |
| LC7821/N | NJU7313A | | SANYO |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------------|--------|--------------|
| LC7821/N | NJU7316 | Note 4 | SANYO |
| LC7822/N | NJU7312A | | SANYO |
| LC7822/N | NJU7315 | Note 4 | SANYO |
| LC7823/N | NJU7311A | | SANYO |
| LC7823/N | NJU7314 | Note 4 | SANYO |
| LF11201D | NJU201AD | | NATIONAL |
| LF347M | NJM074M | Note 1 | NATIONAL |
| LF347N | NJM074D | | NATIONAL |
| LF353D | NJM353M | Note 1 | MOTOROLA |
| LF353M | NJM353M | Note 1 | NATIONAL |
| LF353N | NJM353D | | MOTOROLA |
| LF353N | NJM353D | | NATIONAL |
| LH155A | NJU6575A | Note 4 | SHARP |
| LH155A | NJU6575A | | SHARP |
| LH155B | NJU6676 | Note 4 | SHARP |
| LH155B | NJU6676 | | SHARP |
| LH155xx | NJU6677 | Note 4 | SHARP |
| LH155xx | NJU6678 | Note 4 | SHARP |
| LH155XX | NJU6677 | | SHARP |
| LH155XX | NJU6678 | | SHARP |
| LH1590 | NJU6469 | | SHARP |
| LH1591 | NJU6461 | | SHARP |
| LH1592 | NJU6466/65/75/NJU6620 | | SHARP |
| LH1593 | NJU6466/65/75/NJU6620 | | SHARP |
| LH5008 | NJU6468 | | SHARP |
| LM13600M | NJM13600M | Note 1 | NATIONAL |
| LM13600N | NJM13600D | | NATIONAL |
| LM13600N | NJM13600D | | TI |
| LM13600NS | NJM13600M | | TI |
| LM13700M | NJM13700M | Note 1 | NATIONAL |
| LM13700N | NJM13700D | | NATIONAL |
| LM13700N | NJM13700D | | TI |
| LM13700NS | NJM13700NS | | TI |
| LM1458M | NJM1458M | Note 1 | NATIONAL |
| LM1458M | NJM4558E | | NATIONAL |
| LM1458N | NJM1458D | | NATIONAL |
| LM1458N | NJM4558D | | NATIONAL |
| LM1496M | NJM1496M | Note 1 | NATIONAL |
| LM1496N | NJM1496D | | NATIONAL |
| LM185 | NJM2373 | | NATIONAL |
| LM2575 | NJM2367 | | NATIONAL |
| LM2901D | NJM2901E | | MOTOROLA |
| LM2901D | NJM2901E | | TI |
| LM2901D | NJM2901M | Note 1 | MOTOROLA |
| LM2901D | NJM2901M | Note 1 | TI |
| LM2901D | NJM339E | | MOTOROLA |
| LM2901D | NJM339E | | NATIONAL |
| LM2901DBLE | NJM2901V | Note 3 | TI |
| LM2901M | NJM2901E | | NATIONAL |
| LM2901M | NJM2901M | Note 1 | NATIONAL |
| LM2901N | NJM2901N | | MOTOROLA |
| LM2901N | NJM2901N | | NATIONAL |
| LM2901N | NJM2901N | | TI |
| LM2901N | NJM339D | | MOTOROLA |
| LM2901N | NJM339D | | NATIONAL |
| LM2902D | NJM2902E | | TI |
| LM2902D | NJM324E | | MOTOROLA |
| LM2902D | NJM324E | | NATIONAL |
| LM2902D | NJM324M | Note 1 | MOTOROLA |
| LM2902D | NJM324M | Note 1 | NATIONAL |
| LM2902DBLE | NJM2902V | Note 3 | TI |
| LM2902M | NJM2902E | | NATIONAL |
| LM2902M | NJM2902M | Note 1 | NATIONAL |
| LM2902N | NJM2902N | | NATIONAL |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|--------------|-----------------|--------|--------------|
| LM2902N | NJM2902N | | TI |
| LM2902N | NJM324D | | MOTOROLA |
| LM2902N | NJM324D | | NATIONAL |
| LM2902NS | NJM2902M | Note 1 | TI |
| LM2903D | NJM2903E | | MOTOROLA |
| LM2903D | NJM2903E | | TI |
| LM2903D | NJM2903M | Note 1 | MOTOROLA |
| LM2903D | NJM2903M | Note 1 | TI |
| LM2903DB | NJM3902V | Note 3 | TI |
| LM2903M | NJM2903E | | NATIONAL |
| LM2903M | NJM2903M | Note 1 | NATIONAL |
| LM2903N | NJM2903D | | MOTOROLA |
| LM2903N | NJM2903D | | NATIONAL |
| LM2903P | NJM2903D | | TI |
| LM2904D | NJM2904E | | MOTOROLA |
| LM2904D | NJM2904E | | TI |
| LM2904D | NJM2904M | Note 1 | MOTOROLA |
| LM2904D | NJM358E | | MOTOROLA |
| LM2904D | NJM358E | | NATIONAL |
| LM2904DB | NJM2904V | Note 3 | TI |
| LM2904M | NJM2904E | | NATIONAL |
| LM2904M | NJM2904M | Note 1 | NATIONAL |
| LM2904N | NJM2904D | | MOTOROLA |
| LM2904N | NJM2904D | | NATIONAL |
| LM2904N | NJM358D | | MOTOROLA |
| LM2904N | NJM358D | | NATIONAL |
| LM2904P | NJM2904D | | TI |
| LM2904PS | NJM2904M | Note 1 | TI |
| LM2930KC-5.0 | NJM2930F05 | Note 2 | TI |
| LM2930KC-8.0 | NJM2930F08 | Note 2 | TI |
| LM2930LP-5.0 | NJM2930L05 | | TI |
| LM2930LP-8.0 | NJM2930L08 | | TI |
| LM2930T-5.0 | NJM2930F05 | Note2 | NATIONAL |
| LM2930T-8.0 | NJM2930F08 | Note2 | NATIONAL |
| LM2931Z-5.0 | NJM2930L05 | | NATIONAL |
| LM311D | NJM311D | | NATIONAL |
| LM311D | NJM311E | | MOTOROLA |
| LM311D | NJM311E | | PHILIPS |
| LM311D | NJM311E | | TI |
| LM311D | NJM311M | Note 1 | MOTOROLA |
| LM311D | NJM311M | Note 1 | PHILIPS |
| LM311M | NJM311E | | NATIONAL |
| LM311M | NJM311M | Note 1 | NATIONAL |
| LM311N | NJM311D | | MOTOROLA |
| LM311N | NJM311D | | PHILIPS |
| LM311P | NJM311D | | TI |
| LM311PS | NJM311M | Note 1 | TI |
| LM317AB | NJM317F | | TI |
| LM317T | NJM317F | Note 2 | MOTOROLA |
| LM317T | NJM317F | Note2 | NATIONAL |
| LM317T | NJM317F | Note 2 | ST MICRO |
| LM318D | NJM318E | | TI |
| LM318M | NJM318E | | NATIONAL |
| LM318M | NJM318M | Note 1 | NATIONAL |
| LM318N | NJM318D | | NATIONAL |
| LM318P | NJM318D | | TI |
| LM318PS | NJM318M | Note 1 | TI |
| LM319D | NJM319E | | PHILIPS |
| LM319D | NJM319M | Note 1 | PHILIPS |
| LM319M | NJM319E | | NATIONAL |
| LM319M | NJM319M | Note 1 | NATIONAL |
| LM319N | NJM319D | | NATIONAL |
| LM319N | NJM319D | | PHILIPS |
| LM320LZ-12 | NJM79L12A | | NATIONAL |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------|--------|--------------|
| LM320LZ-15 | NJM79L15A | | NATIONAL |
| LM320LZ-5.0 | NJM79L05A | | NATIONAL |
| LM320T-12 | NJM7912FA | Note 2 | NATIONAL |
| LM320T-15 | NJM7915FA | Note 2 | NATIONAL |
| LM320T-5.0 | NJM7905FA | Note 2 | NATIONAL |
| LM324 SSOP | NJM2902V | Note 3 | MOTOROLA |
| LM324 SSOP | NJM2902V | Note 3 | NATIONAL |
| LM324AN | NJM324DA | | MOTOROLA |
| LM324AN | NJM324DA | | NATIONAL |
| LM324AN | NJM324DA | | ST MICRO |
| LM324AN | NJM324DA | | TI |
| LM324D | NJM2902E | | MOTOROLA |
| LM324D | NJM2902E | | NATIONAL |
| LM324D | NJM2902M | Note 1 | MOTOROLA |
| LM324D | NJM2902M | Note 1 | NATIONAL |
| LM324D | NJM324E | | MOTOROLA |
| LM324D | NJM324E | | TI |
| LM324D | NJM324M | Note 1 | MOTOROLA |
| LM324M | NJM324E | | NATIONAL |
| LM324M | NJM324M | Note 1 | NATIONAL |
| LM324N | NJM2902N | | NATIONAL |
| LM324N | NJM324D | | MOTOROLA |
| LM324N | NJM324D | | NATIONAL |
| LM324N | NJM324D | | TI |
| LM324NS | NJM324M | Note 1 | TI |
| LM324P | NJM2902N | | MOTOROLA |
| LM336 | NJM431 | | NATIONAL |
| LM339 SSOP | NJM2901V | Note 3 | MOTOROLA |
| LM339 SSOP | NJM2901V | Note 3 | NATIONAL |
| LM339D | NJM2901E | | MOTOROLA |
| LM339D | NJM2901E | | NATIONAL |
| LM339D | NJM2901M | Note 1 | MOTOROLA |
| LM339D | NJM2901M | Note 1 | NATIONAL |
| LM339D | NJM339E | | MOTOROLA |
| LM339D | NJM339E | | TI |
| LM339M | NJM339E | | NATIONAL |
| LM339N | NJM2901N | | NATIONAL |
| LM339N | NJM339D | | MOTOROLA |
| LM339N | NJM339D | | NATIONAL |
| LM339N | NJM339D | | TI |
| LM339P | NJM2901N | | MOTOROLA |
| LM340T-10 | NJM7810FA | Note 2 | NATIONAL |
| LM340T-12 | NJM7812FA | Note 2 | MOTOROLA |
| LM340T-12 | NJM7812FA | Note 2 | NATIONAL |
| LM340T-15 | NJM7815FA | Note 2 | MOTOROLA |
| LM340T-15 | NJM7815FA | Note 2 | NATIONAL |
| LM340T-18 | NJM7818FA | Note 2 | MOTOROLA |
| LM340T-24 | NJM7824FA | Note 2 | MOTOROLA |
| LM340T-5.0 | NJM7805FA | Note 2 | MOTOROLA |
| LM340T-5.0 | NJM7805FA | Note 2 | NATIONAL |
| LM340T-6.0 | NJM7806FA | Note 2 | MOTOROLA |
| LM340T-8.0 | NJM7808FA | Note 2 | MOTOROLA |
| LM341T-12 | NJM78M12FA | Note 2 | NATIONAL |
| LM341T-15 | NJM78M15FA | Note 2 | NATIONAL |
| LM341T-5.0 | NJM78M05FA | Note 2 | NATIONAL |
| LM348M | NJM4741M | Note 1 | NATIONAL |
| LM348N | NJM4741D | | NATIONAL |
| LM349M | NJM4741M | Note 1 | NATIONAL |
| LM349N | NJM4741D | | NATIONAL |
| LM358D | NJM358E | | MOTOROLA |
| LM358D | NJM358E | | TI |
| LM358M | NJM358E | | NATIONAL |
| LM358N | NJM358D | | MOTOROLA |
| LM358N | NJM358D | | NATIONAL |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|---------------|-----------------|-----------------|--------------|
| LM358P | NJM358D | | TI |
| LM360M | NJM360E | | NATIONAL |
| LM360M | NJM360M | Note 1 | NATIONAL |
| LM360N | NJM360D | | NATIONAL |
| LM386M-1 (-3) | NJM386E | | NATIONAL |
| LM386M-1 (-3) | NJM386M | Note 1 | NATIONAL |
| LM386M-1 (-3) | NJM386M | Note 1 | NATIONAL |
| LM386M-4 | NJM386BE | | NATIONAL |
| LM386M-4 | NJM386BM | Note 1 | NATIONAL |
| LM386N-1 (-3) | NJM386D | | NATIONAL |
| LM386N-1 (-3) | NJM387D | Note 1 | NATIONAL |
| LM386N-4 | NJM386BD | | NATIONAL |
| LM387M | NJM387M | Note 1 | NATIONAL |
| LM3900N | NJM3900N | | MOTOROLA |
| LM393ACZ | NJM2903L | | NATIONAL |
| LM393D | NJM2903E | | MOTOROLA |
| LM393D | NJM2903E | | NATIONAL |
| LM393D | NJM2903M | Note 1 | MOTOROLA |
| LM393D | NJM2903M | Note 1 | NATIONAL |
| LM393D | NJM2903MG | Note 1 | MOTOROLA |
| LM393D | NJM2903MG | Selected-Note 1 | MOTOROLA |
| LM393D | NJM2903MG | Selected-Note 1 | NATIONAL |
| LM393D | NJM2903MG | Note 1 | TI |
| LM393LP | NJM2903L | | MOTOROLA |
| LM393M | NJM2903MG | Note 1 | NATIONAL |
| LM393N | NJM2903D | | NATIONAL |
| LM393N | NJM2903DQ | | MOTOROLA |
| LM393N | NJM2903DQ | | NATIONAL |
| LM393N | NJM2903DQ | Selected | NATIONAL |
| LM393P | NJM2903D | | MOTOROLA |
| LM393P | NJM2903DQ | Selected | MOTOROLA |
| LM393P | NJM2903DQ | | TI |
| LM3940 | NJM2391 | Note 4 | NATIONAL |
| LM3940 | NJM2391 | | NATIONAL |
| LM4250CM | NJM4250E | | NATIONAL |
| LM4250CM | NJM4250M | Note 1 | NATIONAL |
| LM4250CN | NJM4250D | | NATIONAL |
| LM431ACM | NJM431E | | NATIONAL |
| LM431ACM | NJM431M | Note 1 | NATIONAL |
| LM431ACZ | NJM431L | | NATIONAL |
| LM4864 | NJM2770 | Note 4 | NATIONAL |
| LM555CM | NJM555E | | NATIONAL |
| LM555CM | NJM555M | Note 1 | NATIONAL |
| LM555CN | NJM555D | | NATIONAL |
| LM556CM | NJM556M | Note 1 | NATIONAL |
| LM556CN | NJM556D | | NATIONAL |
| LM567CM | NJM567M | Note 1 | NATIONAL |
| LM567CN | NJM567D | | NATIONAL |
| LM592M | NJM592M | Note 1 | NATIONAL |
| LM592N | NJM592D | | NATIONAL |
| LM723 SMT | NJM723M | Note 1 | ST MICRO |
| LM723CM | NJM723M | Note 1 | NATIONAL |
| LM723CN | NJM723D | | NATIONAL |
| LM723N | NJM723D | | ST MICRO |
| LM741CM | NJM741E | | NATIONAL |
| LM741CM | NJM741M | Note 1 | NATIONAL |
| LM741CN | NJM741D | | NATIONAL |
| LM7805CT | NJM7805FA | Note 2 | NATIONAL |
| LM7806CT | NJM7806FA | Note 2 | NATIONAL |
| LM7808CT | NJM7808FA | Note 2 | NATIONAL |
| LM7812CT | NJM7812FA | Note 2 | NATIONAL |
| LM7815CT | NJM7815FA | Note 2 | NATIONAL |
| LM7818CT | NJM7818FA | Note 2 | NATIONAL |
| LM7824CT | NJM7824FA | Note 2 | NATIONAL |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------|---------------------|--------------|
| LM78L05ACZ | NJM78L05A | | NATIONAL |
| LM78L06ACZ | NJM78L06A | Vo=6.2V on NSC | NATIONAL |
| LM78L08ACZ | NJM78L08A | Vo=8.2V on NSC | NATIONAL |
| LM78L09ACZ | NJM78L09A | | NATIONAL |
| LM78L12ACZ | NJM78L12A | | NATIONAL |
| LM78L15ACZ | NJM78L15A | | NATIONAL |
| LM78M05CT | NJM78M05FA | Note 2 | NATIONAL |
| LM78M06CT | NJM78M06FA | Note 2 | NATIONAL |
| LM78M08CT | NJM78M08FA | Note 2 | NATIONAL |
| LM78M12CT | NJM78M12FA | Note 2 | NATIONAL |
| LM78M15CT | NJM78M15FA | Note 2 | NATIONAL |
| LM78M24CT | NJM78M24FA | Note 2 | NATIONAL |
| LM7905CT | NJM7905FA | Note 2 | NATIONAL |
| LM7908CT | NJM7908FA | Note 2 | NATIONAL |
| LM7912CT | NJM7912FA | Note 2 | NATIONAL |
| LM7915CT | NJM7915FA | Note 2 | NATIONAL |
| LM79L05ACZ | NJM79L05A | | NATIONAL |
| LM79L12ACZ | NJM79L12A | | NATIONAL |
| LM79L15ACZ | NJM79L15A | | NATIONAL |
| LM79M05CT | NJM79M05FA | Note 2 | NATIONAL |
| LM79M08CT | NJM79M08FA | Note 2 | NATIONAL |
| LM79M12CT | NJM79M12FA | Note 2 | NATIONAL |
| LM79M15CT | NJM79M15FA | Note 2 | NATIONAL |
| LM833D | NJM2068E | | MOTOROLA |
| LM833M | NJM2068E | | NATIONAL |
| LM833M | NJM2068M | Note 1 | NATIONAL |
| LM833N | NJM2068D | | MOTOROLA |
| LM833N | NJM2068D | | NATIONAL |
| LMC6022M | NJU7022M | Note 1 | NATIONAL |
| LMC6022N | NJU7022D | | NATIONAL |
| LMC6024M | NJU7024M | Note 1 | NATIONAL |
| LMC6024N | NJU7024D | | NATIONAL |
| LMC6032M | NJU7032M | Note 1 | NATIONAL |
| LMC6032N | NJU7032D | | NATIONAL |
| LMC6034M | NJU7034M | Note 1 | NATIONAL |
| LMC6034N | NJU7034D | | NATIONAL |
| LMC6041AM | NJU7051M | Note 1 Top =-40-85C | NATIONAL |
| LMC6041AN | NJU7051D | Top= -40-85C NSC | NATIONAL |
| LMC6041M | NJU7051M | Note 1 Top =-40-85C | NATIONAL |
| LMC6041N | NJU7051D | Top= -40-85C NSC | NATIONAL |
| LMC6042AM | NJU7052M | Note 1 Top =-40-85C | NATIONAL |
| LMC6042AN | NJU7052D | Top= -40-85C NSC | NATIONAL |
| LMC6042M | NJU7052M | Note 1 Top =-40-85C | NATIONAL |
| LMC6042N | NJU7052D | Top= -40-85C NSC | NATIONAL |
| LMC6044AM | NJU7054M | Note 1 Top =-40-85C | NATIONAL |
| LMC6044AN | NJU7054D | Top= -40-85C NSC | NATIONAL |
| LMC6044M | NJU7054M | Note 1 Top =-40-85C | NATIONAL |
| LMC6044N | NJU7054D | Top= -40-85C NSC | NATIONAL |
| LMC660AIM | NJU7064M | Note 1 | NATIONAL |
| LMC660AIM | NJU7074M | Note 1 | NATIONAL |
| LMC660AIN | NJU7064D | | NATIONAL |
| LMC660AIN | NJU7074D | | NATIONAL |
| LMC660CM | NJU7024M | Note 1 | NATIONAL |
| LMC660CM | NJU7034M | Note 1 | NATIONAL |
| LMC660CN | NJU7024D | | NATIONAL |
| LMC660CN | NJU7034D | | NATIONAL |
| LMC662AIM | NJU7062M | Note 1 | NATIONAL |
| LMC662AIM | NJU7072M | Note 1 | NATIONAL |
| LMC662AIN | NJU7062D | | NATIONAL |
| LMC662AIN | NJU7072D | | NATIONAL |
| LMC662CM | NJU7022M | Note 1 | NATIONAL |
| LMC662CM | NJU7032M | Note 1 | NATIONAL |
| LMC662CN | NJU7022D | | NATIONAL |
| LMC662CN | NJU7032D | | NATIONAL |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------|------------------------|--------------|
| LMC7101BIM | NJU7041F | Note 4 | NATIONAL |
| LMC7101BIM | NJU7042F | Note 4 | NATIONAL |
| LP2980 | NJM2370 | | NATIONAL |
| LP2980 | NJM2370 | | NATIONAL |
| LPC661IM | NJU7071M | Note 1, Icc(max)=0.1mA | NATIONAL |
| LPC661IN | NJU7071D | Icc(max)=0.1mA NSC | NATIONAL |
| LTC1013CN | NJM2119D | | LINEAR TECH |
| LTC1013DS | NJM2119M | Note 1 | LINEAR TECH |
| LV1010 | NJU9701 | Note 4 | SANYO |
| LV1030/1035 | NJW1103 | Note 4, 6 | SANYO |
| LV1030/1035 | NJW1104 | Note 4, 6 | SANYO |
| M34220M4 | NJU3504 | | MITSUBISHI |
| M34225M2 | NJU3503 | | MITSUBISHI |
| M34510M2 | NJU3503 | | MITSUBISHI |
| M34510M4 | NJU3504 | | MITSUBISHI |
| M34510MB | NJU3505 | | MITSUBISHI |
| M50253P | NJU3713 | | MITSUBISHI |
| M502655P | NJU3715 | | MITSUBISHI |
| M50721 | NJU3502 | | MITSUBISHI |
| M50727 | NJU3504 | | MITSUBISHI |
| M50925 | NJU3503 | | MITSUBISHI |
| M50927 | NJU3504 | | MITSUBISHI |
| M51406 | NJW1300 | | MITSUBISHI |
| M51593 | NJM2117 | | MITSUBISHI |
| M5201FP | NJM2120M | Note 1 | MITSUBISHI |
| M5201L | NJM2120L | | MITSUBISHI |
| M5201P | NJM2120D | | MITSUBISHI |
| M5203FP | NJM2121M | Note 1 | MITSUBISHI |
| M5203L | NJM2121L | | MITSUBISHI |
| M5203P | NJM2121D | | MITSUBISHI |
| M5209FP | NJM4562M | Note 1 | MITSUBISHI |
| M5209P | NJM4562D | | MITSUBISHI |
| M5216FP | NJM4556AM | Note 1 | MITSUBISHI |
| M5216P | NJM4556AD | | MITSUBISHI |
| M5218FP | NJM4558M | Note 1 | MITSUBISHI |
| M5218P | NJM4558D | | MITSUBISHI |
| M5219FP | NJM4562M | Note 1 | MITSUBISHI |
| M5219P | NJM4562D | | MITSUBISHI |
| M5220 | NJM2043D | | MITSUBISHI |
| M5220FP | NJM2043M | Note 1 | MITSUBISHI |
| M5221FP | NJM072BM | Note 1 | MITSUBISHI |
| M5221FP | NJM082BM | Note 1 | MITSUBISHI |
| M5221P | NJM072BD | | MITSUBISHI |
| M5221P | NJM082BD | | MITSUBISHI |
| M5223FP | NJM2904M | Note 1 | MITSUBISHI |
| M5223P | NJM2904D | | MITSUBISHI |
| M5224FP | NJM2902M | Note 1 | MITSUBISHI |
| M5224FP | NJM324M | Note 1 | MITSUBISHI |
| M5224P | NJM2902N | | MITSUBISHI |
| M5224P | NJM324D | | MITSUBISHI |
| M5228FP | NJM2058M | Note 1 | MITSUBISHI |
| M5228FP | NJM4741M | Note 1 | MITSUBISHI |
| M5228P | NJM2058D | | MITSUBISHI |
| M5228P | NJM4741D | | MITSUBISHI |
| M5233FP | NJM2903M | Note 4 | MITSUBISHI |
| M5233P | NJM2903D | | MITSUBISHI |
| M5234FP | NJM2901M | Note 4 | MITSUBISHI |
| M5234P | NJM2901N | | MITSUBISHI |
| M5238FP | NJM2082M | Note 1 | MITSUBISHI |
| M5238P | NJM2082D | | MITSUBISHI |
| M5260FP | NJM4560E | | MITSUBISHI |
| M5260FP | NJM4560M | Note 1 | MITSUBISHI |
| M5260FP | NJM4565M | Note 1 | MITSUBISHI |
| M5260P | NJM4560D | | MITSUBISHI |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-------------------|-------------------|--------------|
| M5260P | NJM4565D | | MITSUBISHI |
| M62436FP | NJM2193 | Note 4, 6 | MITSUBISHI |
| M62438FP | NJM2179 | Note 4, 6 | MITSUBISHI |
| M62438FP | NJM2179 | | MITSUBISHI |
| M62455FP | NJM2199 | | MITSUBISHI |
| M62458FP | NJM2190 | Note 4, 6 | MITSUBISHI |
| M62458FP | NJM2191 | | MITSUBISHI |
| M62458FP | NJM2192 | | MITSUBISHI |
| M62459FP | NJM2178 | Note 4, 6 | MITSUBISHI |
| M62461FP | NJW1106 | Note 4, 6 | MITSUBISHI |
| M62464FP | NJW1104 + NJW1131 | Note 4, 6 | MITSUBISHI |
| M62477 | NJM2133 | Note 4 | MITSUBISHI |
| M62494FP | NJM2198 | Note 4, 6 | MITSUBISHI |
| M69032 | NJM2177A | | MITSUBISHI |
| M751701P | NJU6402B | Note 4 | MITSUBISHI |
| MAX130 | NJU9201B/C | Note 4 | MAXIM |
| MAX131 | NJU9201B/C | Note 4 | MAXIM |
| MAX133 | NJU9210B/C | Note 4 | MAXIM |
| MAX134 | NJU9210B/C | Note 4 | MAXIM |
| MAX136 | NJU9203B | Note 4 | MAXIM |
| MAX138 | NJU9207B | | MAXIM |
| MAX860 | NJU7660 | | MAXIM |
| MAX870 | NJU7665 | Note 4 | MAXIM |
| MB3761 | NJM2078 | | FUJITSU |
| MB3771 | NJM2103 | | FUJITSU |
| MB3773 | NJM2102 | | FUJITSU |
| MB88362 | NJU3713 | Note 4 | FUJITSU |
| MC1372 | NJM1372A | | MOTOROLA |
| MC14051BD | NJU4051BM | Note 1 | MOTOROLA |
| MC14051BP | NJU4051BD | | MOTOROLA |
| MC14052BD | NJU4052BM | Note 1 | MOTOROLA |
| MC14052BP | NJU4052BD | | MOTOROLA |
| MC14053BD | NJU4053BM | Note 1 | MOTOROLA |
| MC14053BP | NJU4053BD | | MOTOROLA |
| MC14066BD | NJU4066BM | Note 1 | MOTOROLA |
| MC14066BP | NJU4066BD | | MOTOROLA |
| MC145403 | NJU6401B | Note 4 | MOTOROLA |
| MC145406 | NJU6402B | Note 4 | MOTOROLA |
| MC1455D | NJM555E | | MOTOROLA |
| MC1455D | NJM555M | Note 1 | MOTOROLA |
| MC1455P1 | NJM555D | | MOTOROLA |
| MC14573 | NJU7021 | Note 4 Iset=20uA | MOTOROLA |
| MC14573 | NJU7022 | Note 4 Iset=20uA | MOTOROLA |
| MC14573 | NJU7024 | Note 4 Iset=20uA | MOTOROLA |
| MC14573 | NJU7031 | Note 4 Iset=200uA | MOTOROLA |
| MC14573 | NJU7032 | Note 4 Iset=200uA | MOTOROLA |
| MC14573 | NJU7034 | Note 4 Iset=200uA | MOTOROLA |
| MC1458D | NJM1458M | Note 1 | MOTOROLA |
| MC1458P | NJM1458D | | TI |
| MC1458P1 | NJM1458D | | MOTOROLA |
| MC1458PS | NJM1458M | Note 1 | TI |
| MC1480 | NJU7222 | | MOTOROLA |
| MC14803A | NJU7201L30 | | MOTOROLA |
| MC14805.2A | NJU7201L52 | | MOTOROLA |
| MC14805A | NJU7201L50 | | MOTOROLA |
| MC1496D | NJM1496M | Note 1 | MOTOROLA |
| MC1496P | NJM1496D | | MOTOROLA |
| MC1723CD | NJM723M | Note 1 | MOTOROLA |
| MC1723CP | NJM723D | | MOTOROLA |
| MC1741CD | NJM741E | | MOTOROLA |
| MC1741CD | NJM741M | Note 1 | MOTOROLA |
| MC1741CP1 | NJM741D | | MOTOROLA |
| MC1776CD | NJM4250E | | MOTOROLA |
| MC1776CD | NJM4250M | Note 1 | MOTOROLA |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|---------------|-----------------|--------|--------------|
| MC1776CP1 | NJM4250D | | MOTOROLA |
| MC33033 | NJM2625 | | MOTOROLA |
| MC33063AD | NJM2360AM | Note 1 | MOTOROLA |
| MC33063AP1 | NJM2360AD | | MOTOROLA |
| MC33063D | NJM2360M | Note 1 | MOTOROLA |
| MC33063P1 | NJM2360D | | MOTOROLA |
| MC33167 | NJM2367 | | MOTOROLA |
| MC33172D | NJM022BE | | MOTOROLA |
| MC33172D | NJM022BM | Note 1 | MOTOROLA |
| MC33172D | NJM2132M | Note 1 | MOTOROLA |
| MC33172P | NJM022BD | | MOTOROLA |
| MC33172P | NJM2132D | | MOTOROLA |
| MC33262 | NJM2375 | | MOTOROLA |
| MC33269 | NJM2391 | Note 4 | MOTOROLA |
| MC3357D | NJM3357M | Note 1 | MOTOROLA |
| MC3357P | NJM3357D | | MOTOROLA |
| MC3359P | NJM3359D | | MOTOROLA |
| MC3362 | NJM2292 | Note 4 | MOTOROLA |
| MC3371 | NJM2292 | Note 4 | MOTOROLA |
| MC3372 | NJM2292 | | MOTOROLA |
| MC3403D | NJM3403AM | Note 1 | MOTOROLA |
| MC3403N | NJM3403AD | | TI |
| MC3403NS | NJM3403AM | Note 1 | TI |
| MC3403P | NJM3403AD | | MOTOROLA |
| MC34063A | NJM2374A | | MOTOROLA |
| MC34063D | NJM2360M | Note 1 | MOTOROLA |
| MC34063P1 | NJM2360D | | MOTOROLA |
| MC34119 | NJM2135 | | MOTOROLA |
| MC34119 | NJM2113 | | MOTOROLA |
| MC34119A | NJM2135 | | MOTOROLA |
| MC34119D | NJM2113E | | MOTOROLA |
| MC34119D | NJM2113M | Note 1 | MOTOROLA |
| MC34119P | NJM2113D | | MOTOROLA |
| MC34167 | NJM2367 | | MOTOROLA |
| MC34182D | NJM2162M | Note 1 | MOTOROLA |
| MC34182P | NJM2162D | | MOTOROLA |
| MC34184D | NJM2164M | Note 1 | MOTOROLA |
| MC34184P | NJM2164D | | MOTOROLA |
| MC34262 | NJM2375 | | MOTOROLA |
| MC3456D | NJM556M | Note 1 | MOTOROLA |
| MC3456P | NJM556D | | MOTOROLA |
| MC4558D | NJM4558E | | MOTOROLA |
| MC4558D | NJM4558M | Note 1 | MOTOROLA |
| MC4558P1 | NJM4558D | | MOTOROLA |
| MC4741D | NJM4741M | Note 1 | MOTOROLA |
| MC4741P | NJM4741D | | MOTOROLA |
| MC62436FP | NJM2193 | | MITSUBISHI |
| MC7805 TO-220 | NJM7805FA | Note 2 | SAMSUNG |
| MC7805CT | NJM7805FA | Note 2 | MOTOROLA |
| MC7806 TO-220 | NJM7806FA | Note 2 | SAMSUNG |
| MC7806CT | NJM7806FA | Note 2 | MOTOROLA |
| MC7808 TO-220 | NJM7808FA | Note 2 | SAMSUNG |
| MC7808CT | NJM7808FA | Note 2 | MOTOROLA |
| MC7809CT | NJM7809FA | Note 2 | MOTOROLA |
| MC7812 TO-220 | NJM7812FA | Note 2 | SAMSUNG |
| MC7812CT | NJM7812FA | Note 2 | MOTOROLA |
| MC7815 TO-220 | NJM7815FA | Note 2 | SAMSUNG |
| MC7815CT | NJM7815FA | Note 2 | MOTOROLA |
| MC7818 TO-220 | NJM7818FA | Note 2 | SAMSUNG |
| MC7818CT | NJM7818FA | Note 2 | MOTOROLA |
| MC7824 TO-220 | NJM7824FA | Note 2 | SAMSUNG |
| MC7824CT | NJM7824FA | Note 2 | MOTOROLA |
| MC78L05 | NJM78L05A | | SAMSUNG |
| MC78L05ACD | NJM78L05EA | | MOTOROLA |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------|--------|--------------|
| MC78L05ACP | NJM78L05A | | MOTOROLA |
| MC78L08ACP | NJM78L08A | | MOTOROLA |
| MC78L12 | NJM78L12A | | SAMSUNG |
| MC78L12ACP | NJM78L12A | | MOTOROLA |
| MC78L15 | NJM78L15A | | SAMSUNG |
| MC78L15ACP | NJM78L15A | | MOTOROLA |
| MC78L18ACP | NJM78L18A | | MOTOROLA |
| MC78L24ACP | NJM78L24A | | MOTOROLA |
| MC78M05 | NJM78M05FA | Note 2 | SAMSUNG |
| MC78M05CDT | NJM78M05DLA | Note 5 | MOTOROLA |
| MC78M05CT | NJM78M05FA | Note 2 | MOTOROLA |
| MC78M06 | NJM78M06FA | Note 2 | SAMSUNG |
| MC78M06CT | NJM78M06FA | Note 2 | MOTOROLA |
| MC78M08 | NJM78M08FA | Note 2 | SAMSUNG |
| MC78M08CDT | NJM78M08DLA | Note 5 | MOTOROLA |
| MC78M08CT | NJM78M08FA | Note 2 | MOTOROLA |
| MC78M12 | NJM78M12FA | Note 2 | SAMSUNG |
| MC78M12CDT | NJM78M12DLA | Note 5 | MOTOROLA |
| MC78M12CT | NJM78M12FA | Note 2 | MOTOROLA |
| MC78M15 | NJM78M15FA | Note 2 | SAMSUNG |
| MC78M15CT | NJM78M15FA | Note 2 | MOTOROLA |
| MC78M18CT | NJM78M18FA | Note 2 | MOTOROLA |
| MC78M20CT | NJM78M20FA | Note 2 | MOTOROLA |
| MC78M24 | NJM78M24FA | Note 2 | SAMSUNG |
| MC78M24CT | NJM78M24FA | Note 2 | MOTOROLA |
| MC7905 | NJM7905FA | Note 2 | SAMSUNG |
| MC7905CT | NJM7905FA | Note 2 | MOTOROLA |
| MC7906 | NJM7906FA | Note 2 | SAMSUNG |
| MC7906CT | NJM7906FA | Note 2 | MOTOROLA |
| MC7908 | NJM7908FA | Note 2 | SAMSUNG |
| MC7908CT | NJM7908FA | Note 2 | MOTOROLA |
| MC7912 | NJM7912FA | Note 2 | SAMSUNG |
| MC7912CT | NJM7912FA | Note 2 | MOTOROLA |
| MC7915 | NJM7915FA | Note 2 | SAMSUNG |
| MC7915CT | NJM7915FA | Note 2 | MOTOROLA |
| MC7918 | NJM7918FA | Note 2 | SAMSUNG |
| MC7918CT | NJM7918FA | Note 2 | MOTOROLA |
| MC7924CT | NJM7924FA | Note 2 | MOTOROLA |
| MC79L05 | NJM79L05FA | Note 2 | SAMSUNG |
| MC79L05ACP | NJM79L05A | | MOTOROLA |
| MC79L05CLP | NJM79L05A | | TI |
| MC79L06 | NJM79L06FA | Note 2 | SAMSUNG |
| MC79L12 | NJM79L12FA | Note 2 | SAMSUNG |
| MC79L12ACP | NJM79L12A | | MOTOROLA |
| MC79L12CLP | NJM79L12A | | TI |
| MC79L15 | NJM79L15FA | Note 2 | SAMSUNG |
| MC79L15ACP | NJM79L15A | | MOTOROLA |
| MC79L15CLP | NJM79L15A | | TI |
| MC79L18ACP | NJM79L18A | | MOTOROLA |
| MC79L24ACP | NJM79L24A | | MOTOROLA |
| MC79M05 | NJM79M05FA | Note 2 | SAMSUNG |
| MC79M05CDT | NJM79M05DLA | Note 5 | MOTOROLA |
| MC79M05CT | NJM79M05FA | Note 2 | MOTOROLA |
| MC79M06 | NJM79M06FA | Note 2 | SAMSUNG |
| MC79M08 | NJM79M08FA | Note 2 | SAMSUNG |
| MC79M08CDT | NJM79M08DLA | Note 5 | MOTOROLA |
| MC79M12 | NJM79M12FA | Note 2 | SAMSUNG |
| MC79M12CDT | NJM79M12DLA | Note 5 | MOTOROLA |
| MC79M12CT | NJM79M12FA | Note 2 | MOTOROLA |
| MC79M15 | NJM79M15FA | Note 2 | SAMSUNG |
| MC79M15CT | NJM79M15FA | Note 2 | MOTOROLA |
| MGA82563 | NJG1301/02 | | HP |
| MGA82563 | NJG1308 | | HP |
| MGA85563 | NJG1102 | Note 4 | HP |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|--------------|-----------------|--------|--------------|
| MGA85563 | NJG1103 | Note 4 | HP |
| MGF7132 | NJG1309 | Note 4 | MITSUBISHI |
| MGF7132 | NJG1701 | Note 4 | MITSUBISHI |
| MIC5245 | NJM2871 | | MICREL |
| MM1035 | NJM2103 | | MITSUMI |
| MM1111 | NJM2233 | | MITSUMI |
| MM1111 | NJM2533 | | MITSUMI |
| MM1113 | NJM2234 | | MITSUMI |
| MM1113 | NJM2534 | | MITSUMI |
| MM1114 | NJM2246 | | MITSUMI |
| MM1117 | NJM2235 | | MITSUMI |
| MM1117 | NJM2535 | | MITSUMI |
| MM1223 | NJM2243 | | MITSUMI |
| MM1223 | NJM2244 | | MITSUMI |
| MM1231 | NJM2283 | | MITSUMI |
| MM1232 | NJM2284 | | MITSUMI |
| MM1233 | NJM2285 | | MITSUMI |
| MM1234 | NJM2286 | | MITSUMI |
| MM1235 | NJM2503 | | MITSUMI |
| MM1236 | NJM2506 | | MITSUMI |
| MM1385 | NJM2870 | | MITSUMI |
| MM1385 | NJM2872 | | MITSUMI |
| MN1500 | NJU3101 | | MEC |
| MN150120 | NJU3502 | | MEC |
| MN150412 | NJU3504 | | MEC |
| MN150609 | NJU3505 | | MEC |
| MN15514 | NJU3102 | | MEC |
| MN1551A | NJU3502 | | MEC |
| MN155201 | NJU3503 | | MEC |
| MN155202 | NJU3503 | | MEC |
| MN158481 | NJU3504 | | MEC |
| MPMX-3003 | NJG1701 | | HP |
| MS003 | NJM2240 | Note 4 | KINSEKI |
| MS003 | NJM2240 | | KINSEKI |
| MSC1191 | NJM2113 | Note 4 | OKI |
| MSC1192 | NJM2113 | Note 4 | OKI |
| MSM5259G | NJU6407CF | Note 4 | OKI |
| MSM58371RS | NJU3713 | | OKI |
| MSM59371 | NJU3715 | | OKI |
| MSM5937RS | NJU3716 | | OKI |
| MSM6222B | NJU6468 | | OTHERS |
| MSM6411A(CK) | NJU3502 | | OTHER |
| MSM6562B | NJU6423B | Note 4 | OKI |
| MST001 | NJM2228 | Note 4 | KINSEKI |
| NC34119A | NJM2135 | | MOTOROLA |
| NE544N | NJM2611D | | PHILIPS |
| NE5532P | NJM5532D | | TI |
| NE5532PS | NJM5532M | Note 1 | TI |
| NE5534P | NJM5534D | | TI |
| NE5534PS | NJM5534M | Note 1 | TI |
| NE555 SMT | NJM555E | | ST MICRO |
| NE555 SMT | NJM555M | Note 1 | ST MICRO |
| NE555D | NJM555E | | TI |
| NE555D | NJM555M | Note 1 | TI |
| NE555N | NJM555D | | ST MICRO |
| NE555P | NJM555D | | TI |
| NE556 SMT | NJM556M | Note 1 | ST MICRO |
| NE556D | NJM556M | Note 1 | TI |
| NE556N | NJM556D | | ST MICRO |
| NE556P | NJM556D | | TI |
| NE567D | NJM567M | Note 1 | PHILIPS |
| NE567N | NJM567D | | PHILIPS |
| NE592D | NJM592M | Note 1 | MOTOROLA |
| NE592D | NJM592M | Note 1 | TI |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|--------------|-----------------------|--------|--------------|
| NE592D8 | NJM592E8 | | PHILIPS |
| NE592D8 | NJM592M8 | Note 1 | PHILIPS |
| NE592N | NJM592D | | MOTOROLA |
| NE592N | NJM592D | | TI |
| NE592N14 | NJM592D | | PHILIPS |
| NE592N8 | NJM592D8 | | PHILIPS |
| NE5932D14 | NJM592M | Note 1 | PHILIPS |
| NS733 | NJM592D | | NATIONAL |
| ON2170 | NJL5163K/93K | | MATSUSHITA |
| ON2170(LA) | NJL5163K-F3 | | MATSUSHITA |
| ON2170(LA) | NJL5193K-F3 | | MATSUSHITA |
| ON2170(LF) | NJL5163K-F1 | | MATSUSHITA |
| ON2170(LF) | NJL5193K-F1 | | MATSUSHITA |
| ON2171 | NJL5165K | | MATSUSHITA |
| ON2180(LF) | NJL5165K | | MATSUSHITA |
| ON2270 | NJL5164K | | MATSUSHITA |
| ON2270(LA) | NJL5164K-F3 | | MATSUSHITA |
| ON2270(LF) | NJL5164K-F1 | | MATSUSHITA |
| ON2280(LF) | NJL5166K | | MATSUSHITA |
| OP07CP | NJMOP-07D | | NATIONAL |
| OP07CP | NJMOP-07D | | TI |
| OP07CPS | NJMOP-07M | Note 1 | TI |
| OP07DD | NJMOP-07M | Note 1 | TI |
| OP07DP | NJMOP-07D | | NATIONAL |
| OP07DP | NJMOP-07D | | TI |
| OP-07M | NJMOP-07M | Note 1 | RAYTHEON |
| OP-07N | NJMOP-07D | | RAYTHEON |
| PAS-B0690 | NJL61H SERIES | | MITUMI |
| PAS-B0690 | NJL81H SERIES | | MITUMI |
| PCF2103 | NJU6469/6461 | | PHILIPS |
| PCF2104 | NJU6469/6461 | | PHILIPS |
| PCF2104 | NJU6466/65/75/NJU6620 | | PHILIPS |
| PCF2105 | NJU6466/65/75/NJU6620 | | PHILIPS |
| PCF2115 | NJU6469/6461 | | PHILIPS |
| PCF2116 | NJU6466/65/75/NJU6620 | | PHILIPS |
| PCF2119 | NJU6635 | | PHILIPS |
| PCF8531 | NJU6455 | Note 4 | PHILIPS |
| PCF8531 | NJU6575A | | PHILIPS |
| PCF8548 | NJU6676 | Note 4 | PHILIPS |
| PG-105 | NJL5164K | | KODENSHI |
| PG-105F | NJL5164K-F1 | | KODENSHI |
| PIC-12043SR | NJL62V SERIES | | KODENSHI |
| PIC-12043TE2 | NJL68H SERIES | | KODENSHI |
| PIC-12043TH | NJL63H SERIES | | KODENSHI |
| PIC-12043TH | NJL64H SERIES | | KODENSHI |
| PIC-12043TH2 | NJL67H SERIES | | KODENSHI |
| PIC-12043TM | NJL61H SERIES | | KODENSHI |
| PIC-12043TM | NJL81H SERIES | | KODENSHI |
| PIC-12043TM2 | NJL61H SERIES | | KODENSHI |
| PIC-12043TM2 | NJL81H SERIES | | KODENSHI |
| PIC16CR54 | NJU3502 | | MICROCHIP |
| PIC16CR57 | NJU3503 | | MICROCHIP |
| PIC16CR57A | NJU3504 | | MICROCHIP |
| PIC16CR58A | NJU3504 | | MICROCHIP |
| PIC17FR44 | NJU3505 | | MICROCHIP |
| PIC-26043LM | NJL65V SERIES | | KODENSHI |
| PR-11/20 | NJL5183K/97K | | CITIZEN |
| PST91xx | NJM2410 | Note 4 | MITSUMI |
| R1111 SERIES | NJU7250 | | RICOH |
| R1112 | NJU7252 | | RICOH |
| R1122 | NJU7253 | | RICOH |
| RC2211N | NJM2211D | | RAYTHEON |
| RC4558D | NJM4558E | | TI |
| RC4558DBLE | NJM4558V | Note 3 | TI |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|--------------|-----------------|--------|--------------|
| RC4558P | NJM4558D | | TI |
| RC4558PS | NJM4558M | Note 1 | TI |
| RE5RL25A | NJU7201L25 | | RICOH |
| RE5RL27A | NJU7201L27 | | RICOH |
| RE5RL30A | NJU7201L30 | | RICOH |
| RE5RL30A | NJU7221L30 | | RICOH |
| RE5RL32A | NJU7201L32 | | RICOH |
| RE5RL35A | NJU7201L35 | | RICOH |
| RE5RL35A | NJU7221L35 | | RICOH |
| RE5RL40A | NJU7201L40 | | RICOH |
| RE5RL45A | NJU7201L45 | | RICOH |
| RE5RL50A | NJU7201L50 | | RICOH |
| RE5RL50A | NJU7221L50 | | RICOH |
| RE5RL52A | NJU7201L52 | | RICOH |
| RE5RL55A | NJU7201L55 | | RICOH |
| RH5RC | NJU7261 | | RICOH |
| RH5RL25A | NJU7201U25 | | RICOH |
| RH5RL27A | NJU7201U27 | | RICOH |
| RH5RL30A | NJU7201U30 | | RICOH |
| RH5RL30A | NJU7221U30 | | RICOH |
| RH5RL32A | NJU7201U32 | | RICOH |
| RH5RL35A | NJU7201U35 | | RICOH |
| RH5RL35A | NJU7221U35 | | RICOH |
| RH5RL40A | NJU7201U40 | | RICOH |
| RH5RL45A | NJU7201U45 | | RICOH |
| RH5RL50A | NJU7201U50 | | RICOH |
| RH5RL50A | NJU7221U50 | | RICOH |
| RH5RL52A | NJU7201U52 | | RICOH |
| RH5RL55A | NJU7201U55 | | RICOH |
| RN5RZ | NJU7241 | | RICOH |
| RPM-600CBR-H | NJL63H SERIES | | ROHM |
| RPM-600CBR-L | NJL51H | | ROHM |
| RPM-600CBR-L | NJL61H SERIES | | ROHM |
| RPM-600CBR-S | NJL51V | | ROHM |
| RPM-600CBR-S | NJL61V SERIES | | ROHM |
| RPM-670CBR-H | NJL67H SERIES | | ROHM |
| RPM-670CBR-L | NJL61H | | ROHM |
| RPM-670CBR-L | NJL81H SERIES | | ROHM |
| RPM-670CBR-S | NJL81V SERIES | | ROHM |
| RPM-6900HS | NJL62V SERIES | | ROHM |
| RPR-220 | NJL5165K | | ROHM |
| RS5C313 | NJU6358 | | RICOH |
| RX5RE | NJU7222 | | RICOH |
| RX5RL | NJU7221 | | RICOH |
| RX5RL | NJU7231 | | RICOH |
| RX5RT series | NJU7240 | Note 4 | RICOH |
| RX5RZ series | NJU7241 | Note 4 | RICOH |
| S-1340 | NJU3501 | | SII |
| S-1341/42/43 | NJU3502 | | SII |
| S-1463AF | NJU3503 | | SII |
| S-14L63AF | NJU3503 | | SII |
| S-3510 | NJU6355 Series | | SEIKO |
| S-3510 | NJU6356 Series | | SEIKO |
| S-4520 | NJU6450 | | SEIKO |
| S-4520 | NJU6452 | | SEIKO |
| S-4520 | NJU6570 | Note 4 | SII |
| S-4520 | NJU6572 | Note 4 | SII |
| S-4520 | NJU6570/NJU6572 | | SII |
| S-4521 | NJU6679 | Note 4 | SII |
| S-4521 | NJU6679 | | SII |
| S-4541 | NJU6578 | Note 4 | SII |
| S-4543 | NJU6455 | Note 4 | SII |
| S-4543 | NJU6575A | | SII |
| S-4544 | NJU6575A | Note 4 | SII |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|--------------|-----------------------|---------------|--------------|
| S-4544 | NJU6575A | | SII |
| S-4545 | NJU6578 | | SII |
| S-4552 | NJU6561 | Note 4 | SII |
| S-4561 | NJU6461 | | SII |
| S-4561 | NJU6469 | | SII |
| S-4561 | NJU6466/65/75/NJU6620 | | SII |
| S-4561 | NJU6520 | | SII |
| S-4562 | NJU6461 | | SII |
| S-4562 | NJU6520 | | SII |
| S-7038AF | NJU5601 | Note 4 | SEIKO |
| S-7040D | NJU5601 | Note 4 | SEIKO |
| S-70L41AF | NJU5601 | Note 4 | SEIKO |
| S-80230AG | NJU7211L30 | | SEIKO |
| S-80230AG-GA | NJU7211U30 | | SEIKO |
| S-80250AG | NJU7211L50 | | SEIKO |
| S-80250AG-GS | NJU7211U50 | | SEIKO |
| S-802XX | NJU7211 | | SII |
| S-81211PG | NJU7201L12 | Vo=1.1V-Seiko | SEIKO |
| S-81211PGPA | NJU7201U12 | Vo=1.1V-Seiko | SEIKO |
| S-81215PG | NJU7201L15 | | SEIKO |
| S-81215PG | NJU7221L15 | | SEIKO |
| S-81215PG-PK | NJU7201U15 | | SEIKO |
| S-81215PG-PK | NJU7221U15 | | SEIKO |
| S-81225PG | NJU7201L25 | | SEIKO |
| S-81225PG-PK | NJU7201U25 | | SEIKO |
| S-81227PG-PZ | NJU7201U27 | | SEIKO |
| S-81230PG | NJU7201L30 | | SEIKO |
| S-81230PG | NJU7221L30 | | SEIKO |
| S-81230PG-PB | NJU7201U30 | | SEIKO |
| S-81230PG-PB | NJU7221U30 | | SEIKO |
| S-81235PG | NJU7201L35 | | SEIKO |
| S-81235PG | NJU7221L35 | | SEIKO |
| S-81235PG-PI | NJU7201U35 | | SEIKO |
| S-81235PG-PI | NJU7221U35 | | SEIKO |
| S-81240PG | NJU7201L40 | | SEIKO |
| S-81240PG-PJ | NJU7201U40 | | SEIKO |
| S-81245PG | NJU7201L45 | | SEIKO |
| S-81245PG-P5 | NJU7201U45 | | SEIKO |
| S-81250PG | NJU7201L50 | | SEIKO |
| S-81250PG | NJU7221L50 | | SEIKO |
| S-81250PG-PD | NJU7201U50 | | SEIKO |
| S-81250PG-PD | NJU7221U50 | | SEIKO |
| S-81252PG | NJU7201L52 | | SEIKO |
| S-81252PG-PL | NJU7201U52 | | SEIKO |
| S-81255PG-TL | NJU7201U55 | | SEIKO |
| S-812XX | NJU7221/31 | | SII |
| S-812XX | NJU7200/21 | | SII |
| S-81330HG | NJU7221L30 | | SEIKO |
| S-81330HG-KB | NJU7221U30 | | SEIKO |
| S-81332HG | NJU7201L32 | | SEIKO |
| S-81332HG-KC | NJU7201U32 | | SEIKO |
| S-81350HG | NJU7221L50 | | SEIKO |
| S-81350HG-KD | NJU7221U50 | | SEIKO |
| S-813XX | NJU7222 | | SII |
| S-8321 | NJU7263 | Note 4 | SII |
| S-8321 | NJU7263 | | SII |
| S-8420 | NJU7281 | | SEIKO |
| S-8435 | NJU7261 | | SII |
| S-8435 | NJU7261 | | SEIKO |
| S-8436 | NJU7261 | | SEIKO |
| SBX1610-52 | NJL63H SERIES | | SONY |
| SBX1610-62 | NJL64H SERIES | | SONY |
| SBX1617-52 | NJL62H SERIES | | SONY |
| SBX1617-52 | NJL82H SERIES | | SONY |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|----------------|-----------------|--------|--------------|
| SBX1618-52 | NJL62V SERIES | | SONY |
| SBX1619-52 | NJL61H SERIES | | SONY |
| SBX1619-52 | NJL81H SERIES | | SONY |
| SBX1658 | NJL81H SERIES | | SONY |
| SBX1658-538 | NJL51V | | SONY |
| SBX1658-538 | NJL61H | | SONY |
| SBX1658-538 | NJL61V SERIES | | SONY |
| SBX1780-52 | NJL61H SERIES | | SONY |
| SBX1780-52 | NJL81H SERIES | | SONY |
| SBX1790 | NJL68H SERIES | | SONY |
| SBX1790 | NJL65V SERIES | | SONY |
| SBX1810-52 | NJL67H SERIES | | SONY |
| SBX8030 | NJL81V SERIES | | SONY |
| SBX8031 | NJL81V SERIES | | SONY |
| SBX8035 | NJL51H | | SONY |
| SBX8035 | NJL61H SERIES | | SONY |
| SC17630 Series | NJU7261 | Note 4 | SEIKO |
| SC17660 | NJU7660 | | SEIKO |
| SC17661 | NJU7670 | Note 4 | SEIKO |
| SC17710 | NJU7231 | | EPSON |
| SC17710 Series | NJU7200 Series | | SEIKO |
| SC17710 Series | NJU7221/31 | | EPSON |
| SC17711 | NJU7211 | | SEIKO |
| SC17711YBA | NJU7211L50 | | SEIKO |
| SC17711YBA | NJU7211U50 | | SEIKO |
| SC17711YDA | NJU7211L40 | | SEIKO |
| SC17711YDA | NJU7211U40 | | SEIKO |
| SC17711YGA | NJU7211L30 | | SEIKO |
| SC17711YGA | NJU7211U30 | | SEIKO |
| SED1181F | NJU6417CF | Note 4 | SEIKO |
| SED1200 | NJU6468 | | EPSON |
| SED1200 | NJU6460A | | EPSON |
| SED1210 | NJU6468 | | EPSON |
| SED1210 | NJU6470 | | EPSON |
| SED1230 | NJU6406B | Note 4 | SEIKO |
| SED1230 | NJU6469 | | EPSON |
| SED1232 | NJU6520 | | EPSON |
| SED1234 | NJU6465 | Note 4 | EPSON |
| SED1240 | NJU6463 | Note 4 | EPSON |
| SED1240 | NJU6464 | Note 4 | EPSON |
| SED1278 | NJU6468 | | EPSON |
| SED1278 | NJU6631 | | EPSON |
| SED1520 | NJU6450A | | SEIKO |
| SED1520 | NJU6452A | | SEIKO |
| SED1520 | NJU6570 | Note 4 | EPSON |
| SED1520 | NJU6572 | Note 4 | EPSON |
| SED1521 | NJU6451A | | SEIKO |
| SED1521 | NJU6453A | | SEIKO |
| SED1529 | NJU6450A/52A | | EPSON |
| SED1530 | NJU6583 | Note 4 | EPSON |
| SED1560 | NJU6455 | Note 4 | SEIKO |
| SED1560 | NJU6676 | Note 4 | EPSON |
| SED1561 | NJU6455 | Note 4 | EPSON |
| SED1561 | NJU6575A | | EPSON |
| SED1565 | NJU6676 | Note 4 | EPSON |
| SED1565 | NJU6677A/B | | EPSON |
| SED1565 | NJU6678A/B | | EPSON |
| SED1565 | NJU6679A/B | | EPSON |
| SED1565 | NJU6682A/B | | EPSON |
| SED1565 | NJU6433 | | EPSON |
| SED1565 | NJU6677 | | EPSON |
| SED1566 | NJU6561 | Note 4 | EPSON |
| SED1567 | NJU6575A | Note 4 | EPSON |
| SED1568 | NJU6675 | Note 4 | EPSON |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|------------------|-----------------|--------|-----------------|
| SED1569 | NJU6577 | Note 4 | EPSON |
| SED1569 | NJU6577S | | EPSON |
| SED1569 | NJU6578 | | EPSON |
| SED1569 | NJU6580 | | EPSON |
| SED1569 | NJU6583 | | EPSON |
| SED1569 | NJU6675 | | EPSON |
| SED1569 | NJU6577S | | EPSON |
| SED1575 | NJU6676 | Note 4 | EPSON |
| SG-105 | NJL5163K/93K | | KODENSHI |
| SG-105F | NJL5163K-F1 | | KODENSHI |
| SG-105F | NJL5193K-F1 | | KODENSHI |
| SG-107F3 | NJL5167K | | KODENSHI |
| SG-108 | NJL5183K/97K | | KODENSHI |
| SG3524N | NJM3524D | | TI |
| SG3524N | NJM3524M | Note 1 | ST MICRO |
| SG3524N | NJM3524M | Note 1 | PHILIPS |
| SG3524NS | NJM3524M | Note 1 | TI |
| SG3524P | NJM3524D | | PHILIPS |
| SG3524P | NJM3524D | | ST MICRO |
| Si7660 DIP | NJU7660D | | SILICONIX/TEMIC |
| Si7660 SMT | NJU7660M | Note 1 | SILICONIX/TEMIC |
| Si7661 DIP | NJU7662D | | SILICONIX/TEMIC |
| Si7661 SMT | NJU7662M | Note 1 | SILICONIX/TEMIC |
| SM5003/21 SERIES | NJU6376 SERIES | | NPC |
| SM5004 SERIES | NJU6366 SERIES | | NPC |
| SM5005/6 series | NJU6395 series | | NPC |
| SM5005/6 series | NJU6395 series | | NPC |
| SM5607 | NJU6333 Series | Note 4 | NPC |
| SM5610H | NJU6324 Series | Note 4 | NPC |
| SM5610H | NJU6324 Series | | NPC |
| SM5610K | NJU6322 Series | Note 4 | NPC |
| SM5610K | NJU6329 Series | Note 4 | NPC |
| SM5610K/19K | NJU6322 Series | | NPC |
| SM5610N | NJU6333 Series | Note 4 | NPC |
| SM5610N/19N | NJU6318 Series | | NPC |
| SM5613H | NJU6339 Series | Note 4 | NPC |
| SM5613H | NJU6339 Series | Note 4 | NPC |
| SM5613H | NJU6374 Series | Note 4 | NPC |
| SM5613H | NJU6374 Series | | NPC |
| SM5613K | NJU6338 Series | Note 4 | NPC |
| SM5613K | NJU6373 Series | Note 4 | NPC |
| SM5613K | NJU6373 Series | | NPC |
| SM5613N/17 | NJU6375 Series | | NPC |
| SM5617 | NJU6375 Series | Note 4 | NPC |
| SM5619H | NJU6324 Series | Note 4 | NPC |
| SM5619K | NJU6322 Series | Note 4 | NPC |
| SM5619K | NJU6329 Series | Note 4 | NPC |
| SM5619N | NJU6330 Series | Note 4 | NPC |
| SM5623N | NJU6391 Series | Note 4 | NPC |
| SM5623N | NJU6392 series | Note 4 | NPC |
| SM5623N | NJU6393 | Note 4 | NPC |
| SM5623N | NJU6392 series | | NPC |
| SM5624N | NJU6319 Series | Note 4 | NPC |
| SM5624N | NJU6319 Series | | NPC |
| SM590 | NJU3101 | | SHARP |
| SM591 | NJU3102 | | SHARP |
| SM595 | NJU3102 | | SHARP |
| SM5K5 | NJU3503 | | SHARP |
| SM5K6 | NJU3504 | | SHARP |
| SM5K7 | NJU3505 | | SHARP |
| SM8210M/11M/12M | NJU5601 | Note 4 | NPC |
| SN75C1406 | NJU6401B | Note 4 | TI |
| SN75C1454 | NJU6402B | Note 4 | TI |
| SPI-315-04 | NJL5163K-F1 | | SANYO |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|---------------|------------------------|-----------|--------------|
| SPI-315-04 | NJL5193K-F1 | | SANYO |
| SPI-315-05 | NJL5164K-F1 | | SANYO |
| SPI-315-24 | NJL5163K-F10 | | SANYO |
| SPI-315-24 | NJL5193K-F10 | | SANYO |
| SPI-315-25 | NJL5164K-F10 | | SANYO |
| SPI-315-34 | NJL5163K-F2 | | SANYO |
| SPI-315-34 | NJL5193K-F2 | | SANYO |
| SPI-315-35 | NJL5164K-F2 | | SANYO |
| SPI-315-44/14 | NJL5163K/93K | | SANYO |
| SPI-315-45/15 | NJL5164K | | SANYO |
| SPI-335-04 | NJL5165K | | SANYO |
| SPI-335-34 | NJL5167K | | SANYO |
| SPM0103A | NJG1103 | | SANYO |
| SPM3202 | NJG1517/22, NJG1518/23 | Note 4 | SANYO |
| SPM3202 | NJG1518/23 | | SANYO |
| SPM3252 | NJG1506/07 | Note 4 | SANYO |
| SPM3255 | NJG1508/09 | Note 4 | SANYO |
| SPM3255 | NJG1508/09 | SIMILAR | SANYO |
| SPS-407-1-D | NJL64H SERIES | | SANYO |
| SPS-408-1-G | NJL65V SERIES | | SANYO |
| SPS-409-1-G | NJL82V SERIES | | SANYO |
| SPS-420-1 | NJL67H SERIES | | SANYO |
| SPS-421-1 | NJL62H SERIES | | SANYO |
| SPS-422-1 | NJL63H SERIES | | SANYO |
| SPS-423-1 | NJL62V SERIES | | SANYO |
| SPS-424-1 | NJL68H SERIES | | SANYO |
| SPS-425-1 | NJL84H SERIES | | SANYO |
| SPS-440 | NJL83H SERIES | | SANYO |
| SPS-442 | NJL88H SERIES | | SANYO |
| SPS-446 | NJL82H SERIES | | SANYO |
| SW-289 | NJG1524 | | MACOM |
| SW-419 | NJG1519 | | MACOM |
| SW-425 | NJG1516 | | MACOM |
| T6C84 | NJU6575A | Note 4 | |
| T7934 | NJU6468 | | |
| TA2136F | NJM2198 | Note 4, 6 | TOSHIBA |
| TA2136F | NJM2178 | | TOSHIBA |
| TA31136 | NJM2292 | | TOSHIBA |
| TA31141 | NJM2294 | Note 4 | TOSHIBA |
| TA31143 | NJM2294 | | TOSHIBA |
| TA31145 | NJM2537 | | TOSHIBA |
| TA75339F | NJM2901M | Note 4 | TOSHIBA |
| TA75339P | NJM2901N | | TOSHIBA |
| TA75393F | NJM2903M | Note 4 | TOSHIBA |
| TA75393P | NJM2903D | | TOSHIBA |
| TA75S01F | NJM2125F | Note 4 | TOSHIBA |
| TA75W01FU | NJM2143R | Note 4 | TOSHIBA |
| TA7736 | NJM262D | | TOSHIBA |
| TA78L006 | NJM78L06UA | | TOSHIBA |
| TA78L008 | NJM78L08UA | | TOSHIBA |
| TA78L009 | NJM78L09UA | | TOSHIBA |
| TA78L018 | NJM78L18UA | | TOSHIBA |
| TA78L020 | NJM78L20UA | | TOSHIBA |
| TA78L05 | NJM78L05A | | TOSHIBA |
| TA78L05 | NJM78L05UA | | TOSHIBA |
| TA78L12 | NJM78L12A | | TOSHIBA |
| TA78L12 | NJM78L12UA | | TOSHIBA |
| TA78L15 | NJM78L15A | | TOSHIBA |
| TA78L15 | NJM78L15UA | | TOSHIBA |
| TA78L24 | NJM78L24A | | TOSHIBA |
| TA78L24 | NJM78L24UA | | TOSHIBA |
| TA79L005 | NJM79L05UA | | TOSHIBA |
| TA79L006 | NJM79L06UA | | TOSHIBA |
| TA79L008 | NJM79L08UA | | TOSHIBA |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------|-----------|--------------|
| TA79L009 | NJM79L09UA | | TOSHIBA |
| TA79L012 | NJM79L12UA | | TOSHIBA |
| TA79L015 | NJM79L15UA | | TOSHIBA |
| TA79L018 | NJM79L18UA | | TOSHIBA |
| TA79L024 | NJM79L24UA | | TOSHIBA |
| TA8795 | NJW1300 | | TOSHIBA |
| TC35906P | NJU6402B | Note 4 | TOSHIBA |
| TC75S51F | NJU7012F | Note 4 | TOSHIBA |
| TC75S51F | NJU7092 | Note 4 | TOSHIBA |
| TC75S54F | NJU7013F | Note 4 | TOSHIBA |
| TC75S55F | NJU7017F | | TOSHIBA |
| TC75S58F | NJU7141 | Note 4 | TOSHIBA |
| TC75W51FU | NJU7015R | Note 4 | TOSHIBA |
| TC75W54FU | NJU7016R | Note 4 | TOSHIBA |
| TC75W55FU | NJU7019R | | TOSHIBA |
| TC9162 | NJU7311A | | TOSHIBA |
| TC9162 | NJU7314 | Note 4 | TOSHIBA |
| TC9163 | NJU7312A | | TOSHIBA |
| TC9163 | NJU7315 | Note 4 | TOSHIBA |
| TC9164 | NJU7313A | | TOSHIBA |
| TC9164 | NJU7316 | Note 4 | TOSHIBA |
| TC9187A | NJU7305 | Note 4 | TOSHIBA |
| TC9243F | NJU6004 | Note 4 | TOSHIBA |
| TC9332F | NJU25008 | | TOSHIBA |
| TC9337F | NJU25018 | Note 4, 6 | TOSHIBA |
| TDA1308 | NJU7082B | Note 4 | PHILIPS |
| TDA2822M | NJM2073D | | ST MICRO |
| TDA7335P | NJM2085M | Note 1 | ST MICRO |
| TEA0675T | NJM2085 | Note 4 | PHILIPS |
| TFMS5XX | NJL85V SERIES | | VISHAY |
| TFMT5XX0 | NJL64H SERIES | | VISHAY |
| TG2006F | NJG1301/02 | Note 4 | TOSHIBA |
| TG2203F/04F | NJG1506/07 | Note 4 | TOSHIBA |
| TG2206F | NJG1508/09 | Note 4 | TOSHIBA |
| TK10487 | NJM2292 | | TOKO |
| TK111xx | NJM2870 | Note 4 | TOKO |
| TK111XX | NJM2872 | | TOKO |
| TK112xx | NJM2370 | | TOKO |
| TL022CD | NJM022BE | | TI |
| TL022CD | NJM022BM | Note 1 | TI |
| TL022CD | NJM022E | | TI |
| TL022CP | NJM022BD | | TI |
| TL022CP | NJM022D | | TI |
| TL022CPS | NJM022M | Note 1 | TI |
| TL062ACD | NJM062MA | Note 1 | MOTOROLA |
| TL062ACD | NJM062MA | Note 1 | TI |
| TL062BCD | NJM062MB | Note 1 | TI |
| TL062CD | NJM062E | | MOTOROLA |
| TL062CD | NJM062E | | TI |
| TL062CD | NJM062M | Note 1 | MOTOROLA |
| TL062CP | NJM062D | | MOTOROLA |
| TL062CP | NJM062D | | TI |
| TL062CPS | NJM062M | Note 1 | TI |
| TL064CD | NJM064M | Note 1 | MOTOROLA |
| TL064CN | NJM064D | | TI |
| TL064CNS | NJM064M | Note 1 | TI |
| TL064CP | NJM064D | | MOTOROLA |
| TL072BCP | NJM072BMB | Note 1 | TI |
| TL072CD | NJM072M | Note 1 | MOTOROLA |
| TL072CM | NJM072M | Note 1 | NATIONAL |
| TL072CP | NJM072D | | MOTOROLA |
| TL072CP | NJM072D | | NATIONAL |
| TL072CP | NJM072D | | TI |
| TL072CPS | NJM072M | Note 1 | TI |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------|--------|--------------|
| TL074CD | NJM074M | Note 1 | MOTOROLA |
| TL074CN | NJM074D | | TI |
| TL074CNS | NJM074M | Note 1 | TI |
| TL074CP | NJM074D | | MOTOROLA |
| TL082CD | NJM082E | | MOTOROLA |
| TL082CD | NJM082E | | TI |
| TL082CD | NJM082M | Note 1 | MOTOROLA |
| TL082CD | NJM2082M | Note 1 | MOTOROLA |
| TL082CD | NJM2082M | Note 1 | TI |
| TL082CM | NJM082E | | NATIONAL |
| TL082CM | NJM082M | Note 1 | NATIONAL |
| TL082CM | NJM2082M | Note 1 | NATIONAL |
| TL082CP | NJM082D | | MOTOROLA |
| TL082CP | NJM082D | | NATIONAL |
| TL082CP | NJM082D | | TI |
| TL082CP | NJM2082D | | MOTOROLA |
| TL082CP | NJM2082D | | NATIONAL |
| TL082CP | NJM2082D | | TI |
| TL082CPS | NJM082M | Note 1 | TI |
| TL084CD | NJM084M | Note 1 | MOTOROLA |
| TL084CN | NJM084D | | TI |
| TL084CNS | NJM084M | Note 1 | TI |
| TL084CP | NJM084D | | MOTOROLA |
| TL431ACD | NJM431MA | Note 1 | TI |
| TL431ACPK | NJM431UA | | TI |
| TL431AD | NJM431MA | Note 1 | MOTOROLA |
| TL431CD | NJM431E | | MOTOROLA |
| TL431CD | NJM431E | | TI |
| TL431CLP | NJM431L | | TI |
| TL431CP | NJM431D | | TI |
| TL431CPK | NJM431U | | TI |
| TL431D | NJM431M | Note 1 | MOTOROLA |
| TL431LP | NJM431L | | MOTOROLA |
| TL431P | NJM431D | | MOTOROLA |
| TL431PS | NJM431M | Note 1 | TI |
| TL5001 | NJM2381 | Note 4 | TI |
| TL5001 | NJM2381 | | TI |
| TLC2272CD | NJU7072M | Note 1 | TI |
| TLC2272CP | NJU7072D | | TI |
| TLC2272CP | NJU7074D | | TI |
| TLC2274CD | NJU7074M | Note 1 | TI |
| TLC271BCD | NJU7051M | Note 1 | TI |
| TLC271BCD | NJU7061M | Note 1 | TI |
| TLC271BCD | NJU7071M | Note 1 | TI |
| TLC271BCP | NJU7051D | | TI |
| TLC271BCP | NJU7061D | | TI |
| TLC271BCP | NJU7071D | | TI |
| TLC271CD | NJU7001M | Note 1 | TI |
| TLC271CD | NJU7021M | Note 1 | TI |
| TLC271CD | NJU7031M | Note 1 | TI |
| TLC271CP | NJU7001D | | TI |
| TLC271CP | NJU7021D | | TI |
| TLC271CP | NJU7031D | | TI |
| TLC272BCD | NJU7072M | Note 1 | TI |
| TLC272BCP | NJU7072D | | TI |
| TLC272CD | NJU7032M | Note 1 | TI |
| TLC272CP | NJU7032D | | TI |
| TLC274BCD | NJU7074M | Note 1 | TI |
| TLC274BCP | NJU7074D | | TI |
| TLC274CD | NJU7034M | Note 1 | TI |
| TLC274CP | NJU7034D | | TI |
| TLC27L2BCD | NJU7052M | Note 1 | TI |
| TLC27L2BCP | NJU7052D | | TI |
| TLC27L2CD | NJU7002M | Note 1 | TI |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-----------------|-----------------|--------|--------------|
| TLC27L2CP | NJU7002D | | TI |
| TLC27L4BCD | NJU7054M | Note 1 | TI |
| TLC27L4BCP | NJU7054D | | TI |
| TLC27L4CD | NJU7004M | Note 1 | TI |
| TLC27L4CP | NJU7004D | | TI |
| TLC27M2BCD | NJU7062M | Note 1 | TI |
| TLC27M2BCP | NJU7062D | | TI |
| TLC27M2CD | NJU7022M | Note 1 | TI |
| TLC27M2CP | NJU7022D | | TI |
| TLC27M4BCD | NJU7064M | Note 1 | TI |
| TLC27M4BCP | NJU7064D | | TI |
| TLC27M4CD | NJU7024M | Note 1 | TI |
| TLC27M4CP | NJU7024D | | TI |
| TLC339CD | NJU7114AM | Note 1 | TI |
| TLC339CP | NJU7114AD | | TI |
| TLC3702CD | NJU7102AM | Note 1 | TI |
| TLC3702CP | NJU7102AD | | TI |
| TLC3704CD | NJU7104AM | Note 1 | TI |
| TLC3704CP | NJU7104AD | | TI |
| TLC393CD | NJU7112AM | Note 1 | TI |
| TLC393CP | NJU7112AD | | TI |
| TLP907 | NJL5164K | | TOSHIBA |
| TLP907(LB) | NJL5164K-F1 | | TOSHIBA |
| TLP908 | NJL5163K/93K | | TOSHIBA |
| TLP908(LB) | NJL5163K-F1 | | TOSHIBA |
| TLP908(LB) | NJL5193K-F1 | | TOSHIBA |
| TLP910 | NJL5181K/96K | | TOSHIBA |
| TMP47C101 | NJU3502 | | TOSHIBA |
| TMP47C102 | NJU3502 | | TOSHIBA |
| TMP47C103 | NJU3502 | | TOSHIBA |
| TMP47C242B | NJU3503 | | TOSHIBA |
| TMP47C440A | NJU3504 | | TOSHIBA |
| TMP47C443 | NJU3504 | | TOSHIBA |
| TS271BCD (high) | NJU7071M | Note 1 | ST MICRO |
| TS271BCD (low) | NJU7051M | Note 1 | ST MICRO |
| TS271BCD (med) | NJU7061M | Note 1 | ST MICRO |
| TS271BCN (high) | NJU7071D | | ST MICRO |
| TS271BCN (low) | NJU7051D | | ST MICRO |
| TS271BCN (med) | NJU7061D | | ST MICRO |
| TS271CD (high) | NJU7031M | Note 1 | ST MICRO |
| TS271CD (low) | NJU7001M | Note 1 | ST MICRO |
| TS271CD (med) | NJU7021M | Note 1 | ST MICRO |
| TS271CN (high) | NJU7031D | | ST MICRO |
| TS271CN (low) | NJU7001D | | ST MICRO |
| TS271CN (med) | NJU7021D | | ST MICRO |
| TS272BCD | NJU7072M | Note 1 | ST MICRO |
| TS272BCN | NJU7072D | | ST MICRO |
| TS272CD | NJU7032M | Note 1 | ST MICRO |
| TS272CN | NJU7032D | | ST MICRO |
| TS274BCD | NJU7074M | Note 1 | ST MICRO |
| TS274BCN | NJU7074D | | ST MICRO |
| TS274CD | NJU7034M | Note 1 | ST MICRO |
| TS274CN | NJU7034D | | ST MICRO |
| TS27L2BCD | NJU7052M | Note 1 | ST MICRO |
| TS27L2BCN | NJU7052D | | ST MICRO |
| TS27L2CD | NJU7002M | Note 1 | ST MICRO |
| TS27L2CN | NJU7002D | | ST MICRO |
| TS27L4BCD | NJU7054M | Note 1 | ST MICRO |
| TS27L4BCN | NJU7054D | | ST MICRO |
| TS27L4CD | NJU7004M | Note 1 | ST MICRO |
| TS27L4CN | NJU7004D | | ST MICRO |
| TS27M2BCD | NJU7062M | Note 1 | ST MICRO |
| TS27M2BCN | NJU7062D | | ST MICRO |
| TS27M2CD | NJU7022M | Note 1 | ST MICRO |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|-------------|-----------------|------------|--------------|
| TS27M2CN | NJU7022D | | ST MICRO |
| TS27M4BCD | NJU7064M | Note 1 | ST MICRO |
| TS27M4BCN | NJU7064D | | ST MICRO |
| TS27M4CD | NJU7024M | Note 1 | ST MICRO |
| TS27M4CN | NJU7024D | | ST MICRO |
| TS339CD | NJU7114AM | Note 1 | ST MICRO |
| TS339CN | NJU7114AD | | ST MICRO |
| TS3702CD | NJU7102AM | Note 1 | ST MICRO |
| TS3702CN | NJU7102AD | | ST MICRO |
| TS3704CD | NJU7104AM | Note 1 | ST MICRO |
| TS3704CN | NJU7104AD | | ST MICRO |
| TS393CD | NJU7112AM | Note 1 | ST MICRO |
| TS393CN | NJU7112AD | | ST MICRO |
| TSOP11XX | NJL62V SERIES | | VISHAY |
| TSOP12XX | NJL65V SERIES | | VISHAY |
| TSOP17XX | NJL82V SERIES | | VISHAY |
| TSOP18xx | NJL51V | | VISHAY |
| TSOP18XX | NJL61V SERIES | | VISHAY |
| UA723CD | NJM723M | Note 1 | TI |
| UA723CN | NJM723D | | TI |
| UA741CD | NJM741E | | TI |
| UA741CP | NJM741D | | TI |
| UA741CPS | NJM741M | Note 1 | TI |
| UA7805CKC | NJM7805FA | Note 2 | TI |
| UA7806CKC | NJM7806FA | Note 2 | TI |
| UA7808CKC | NJM7808FA | Note 2 | TI |
| UA7810CKC | NJM7810FA | Note 2 | TI |
| UA7812CKC | NJM7812FA | Note 2 | TI |
| UA7815CKC | NJM7815FA | Note 2 | TI |
| UA7818CKC | NJM7818FA | Note 2 | TI |
| UA7824CKC | NJM7824FA | Note 2 | TI |
| UA78L02CKC | NJM78L02A | | TI |
| UA78L05CLP | NJM78L05UA | | TI |
| UA78L06CLP | NJM78L06A | Vo=6.2V TI | TI |
| UA78L08CLP | NJM78L08A | | TI |
| UA78L09CLP | NJM78L09A | | TI |
| UA78L10CLP | NJM78L10UA | | TI |
| UA78L12CLP | NJM78L12A | | TI |
| UA78L15CLP | NJM78L15A | | TI |
| UA78M05CKC | NJM78M05FA | Note 2 | TI |
| UA78M06CKC | NJM78M06FA | Note 2 | TI |
| UA78M08CKC | NJM78M08FA | Note 2 | TI |
| UA78M09CKC | NJM78M09FA | Note 2 | TI |
| UA78M10CKC | NJM78M10FA | Note 2 | TI |
| UA78M12CKC | NJM78M12FA | Note 2 | TI |
| UA78M15CKC | NJM78M15FA | Note 2 | TI |
| UA78M20CKC | NJM78M20FA | Note 2 | TI |
| UA78M24CKC | NJM78M24FA | Note 2 | TI |
| UA7905CKC | NJM7905FA | Note 2 | TI |
| UA7906CKC | NJM7906FA | Note 2 | TI |
| UA7908CKC | NJM7908FA | Note 2 | TI |
| UA7912CKC | NJM7912FA | Note 2 | TI |
| UA7915CKC | NJM7915FA | Note 2 | TI |
| UA7918CKC | NJM7918FA | Note 2 | TI |
| UA7924CKC | NJM7924FA | Note 2 | TI |
| UA79M05CKC | NJM79M05FA | Note 2 | TI |
| UA79M06CKC | NJM79M06FA | Note 2 | TI |
| UA79M08CKC | NJM79M08FA | Note 2 | TI |
| UA79M12CKC | NJM79M12FA | Note 2 | TI |
| UA79M15CKC | NJM79M15FA | Note 2 | TI |
| UA79M24CKC | NJM79M24FA | Note 2 | TI |
| UPC1093 | NJM431 | | NEC |
| UPC1246 | NJM2624 | Note 4 | NEC |
| UPC1246 | NJM2624A | | NEC |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|---------------|-----------------|--------|--------------|
| UPC151C | NJM741D | | NEC |
| UPC151G | NJM741E | | NEC |
| UPC151G | NJM741M | Note 1 | NEC |
| UPC159 DIP | NJM318D | | NEC |
| UPC159 SMT | NJM318E | | NEC |
| UPC159 SMT | NJM318M | Note 1 | NEC |
| UPC177C | NJM2901N | | NEC |
| UPC177G | NJM2901M | Note 4 | NEC |
| UPC1943 | NJM2373 | | NEC |
| UPC258C | NJM4558D | | NEC |
| UPC258G | NJM4558E | | NEC |
| UPC258G | NJM4558M | Note 1 | NEC |
| UPC259C | NJM4565D | | NEC |
| UPC259G | NJM4565M | Note 1 | NEC |
| UPC271C | NJM311D | | NEC |
| UPC271G | NJM311M | Note 4 | NEC |
| UPC272C | NJM319D | | NEC |
| UPC272G | NJM319M | Note 4 | NEC |
| UPC277C | NJM2903D | | NEC |
| UPC277G | NJM2903M | Note 4 | NEC |
| UPC311C | NJM311D | | NEC |
| UPC311G | NJM311M | Note 4 | NEC |
| UPC317 | NJM317 | | NEC |
| UPC318 DIP | NJM318D | | NEC |
| UPC318 SMT | NJM318E | | NEC |
| UPC318 SMT | NJM318M | Note 1 | NEC |
| UPC319C | NJM319D | | NEC |
| UPC319G | NJM319M | Note 4 | NEC |
| UPC339C | NJM2901N | | NEC |
| UPC339G | NJM2901M | Note 4 | NEC |
| UPC393C | NJM2903D | | NEC |
| UPC393G | NJM2903M | Note 4 | NEC |
| UPC4556C | NJM4562D | | NEC |
| UPC4556G | NJM4562M | Note 1 | NEC |
| UPC4558C | NJM4558D | | NEC |
| UPC4558G | NJM4558E | | NEC |
| UPC4558G | NJM4558M | Note 1 | NEC |
| UPC4560C | NJM4565D | | NEC |
| UPC4560G | NJM4565M | Note 1 | NEC |
| UPC4570C | NJM2068D | | NEC |
| UPC4570G | NJM2068E | | NEC |
| UPC4570G | NJM2068M | Note 1 | NEC |
| UPC4570HA | NJM2068L | | NEC |
| UPC4572C | NJM4580D | | NEC |
| UPC4572G | NJM4580E | | NEC |
| UPC4572G | NJM4580M | Note 1 | NEC |
| UPC741C | NJM741D | | NEC |
| UPC741G | NJM741E | | NEC |
| UPC741G | NJM741M | Note 1 | NEC |
| UPC8112 | NJG1552/53/53B | | NEC |
| UPC8112B | NJG1556 | | NEC |
| UPD16432 | NJU6467 | | NEC |
| UPD16432 | NJU6624 | | NEC |
| UPD16432 | NJU6469/6461 | | NEC |
| UPD16434 | NJU6468 | | NEC |
| UPD16437 | NJU6469/6461 | | NEC |
| UPD16670 | NJU6469/6461 | | NEC |
| UPD16675A | NJU6575A | Note 4 | NEC |
| UPD16675A | NJU6575A | | NEC |
| UPD17103/07 | NJU3101 | | NEC |
| UPD17104/08 | NJU3102 | | NEC |
| UPD17120/121 | NJU3502 | | NEC |
| UPD17136A/37A | NJU3503 | | NEC |
| UPD17147 | NJU3503 | | NEC |

NJR Corporation
Cross Reference Guide
Sorted By Part Number

12/12/00

| Part Number | NJR Part Number | Note | Manufacturer |
|---|------------------------|-----------|--------------|
| UPD17149 | NJU3504 | | NEC |
| UPD4711 | NJU6401B | Note 4 | NEC |
| UPD6121 | NJU6004 | Note 4 | NEC |
| UPD6122 | NJU6005 | Note 4 | NEC |
| UPD6123/24/24A | NJU3502 | | NEC |
| UPD6125A/26A | NJU3502 | | NEC |
| UPD6600 | NJU3501 | | NEC |
| UPD75064 | NJU3504 | | NEC |
| UPD75068 | NJU3505 | | NEC |
| UPD7554A/64A | NJU3502 | | NEC |
| UPG131G/132G | NJG1501/02 | Note 4 | NEC |
| UPG152TA | NJG1508/09 | Note 4 | NEC |
| UPG153TB | NJG1518/23 | Note 4 | NEC |
| UPG154/8TB | NJG1517/22 | Note 4 | NEC |
| UPG1548TB | NJG1517/22, NJG1518/23 | Note 4 | NEC |
| UPG154TB | NJG1517/22, NJG1518/23 | Note 4 | NEC |
| UPG157GV | NJG1516 | Note 4 | NEC |
| UPG171GV | NJG1301/02 | Note 4 | NEC |
| UPG2001TG | NJG1520/21 | Note 4 | NEC |
| XC2151 Series | NJU6318 Series | Note 4 | TOREX |
| XC2151 Series | NJU6319 Series | Note 4 | TOREX |
| XC2151 Series | NJU6322 Series | Note 4 | TOREX |
| XC2151 Series | NJU6329 Series | Note 4 | TOREX |
| XC2151 Series | NJU6338 Series | Note 4 | TOREX |
| XC2151 Series | NJU6373 Series | Note 4 | TOREX |
| XC62SP | NJU7241 | | TOREX |
| XC62SP series | NJU7241 | Note 4 | TOREX |
| XR1071 | NJM2153 | Note 4, 6 | EXAR |
| XR1071 | NJM2153 | | EXAR |
| XR1091DCP | NJU7508D | Note 4 | EXAR |
| XR1091DCP | NJU7509 | | EXAR |
| XR1092 | NJU7508D | Note 4 | EXAR |
| XR1092 | NJU7509 | | EXAR |
| XR2211MD | NJM2211M | Note 1 | EXAR |
| XR2211P | NJM2211D | | EXAR |
| XR65119 | NJM2113D | | ROHM |
| XR65119 | NJM2113E | SMT | ROHM |
| XR65119 | NJM2113M | Note 1 | ROHM |
| XRT65119 | NJM2113 | | EXAR |
| XRT65119 | NJM2135 | Note 4 | EXAR |
| YSS-205B | NJU25102 | Note 4 | YAMAHA |
| YSS-215 | NJU25005 | Note 4, 6 | YAMAHA |
| YSS-902 | NJU25301 | | YAMAHA |
| YSS-912 | NJU25301 | Note 4, 6 | YAMAHA |
| Note 1: EIAJ (Electronics Industrial Association of Japan) standard package. The width of the package is slightly wider than the JEDEC std. (US). However, since EIAJ parts have the same lead pitch as JEDEC parts, they can usually be placed on the JEDEC footprint without problems. | | | |
| Note 2: TO-220F (Full Molded TO-220 package) The mechanical dimensions are different due to the encapsulated fin. Please refer to the attached illustration. | | | |
| Note 3: SSOP Package (Shrink SOP Package) is available. | | | |
| Note 4: Devices are functionally equivalent, but NOT pin-to-pin compatible. | | | |
| Note 5: TO-252 or DPACK Package: designated with suffix "DLA" | | | |
| Note 6: Licensable Product. | | | |