

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
BC297 (Cont'd) BCX17 3 PHIN BCX51 3 PHIN D41D7 3 GESY THBC327 3 SPR THBC836 3 SPR	BC309C THBC309C 1 SPR	BC322C BC558B 1 PHIN BCW30 3 PHIN BCW61B 3 PHIN BCW61C 3 PHIN THBC558B 3 SPR	BC332 (Cont'd) THBC547 3 SPR	BC333 BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	BC340 (Cont'd) DE128 3 DGE GES3053 3 GESY THC3053 3 SPR
BC298 BC328 1 PHIN BC107A 3 PHIN BC547A 3 PHIN BCX18 3 PHIN THBC328 3 SPR	BC310 2N1893 1 RCA BC141 1 SGSI 2N5320 3 RCA D40D7 3 GESY D42T1 3 GESY DE128 3 DGE	BC323 2N5320 1 RCA DE128 3 DGE	BC334 BC178 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR	BC340-6 2N2218A 1 PHIN GES2218A 3 GESY THC2218A 3 SPR TN2218A 3 NSC TP2218A 3 SPR	BC350 (Cont'd) BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR
BC300 2N1893 1 RCA BD139 1 PHIN 2N2405 3 RCA 2N2987 3 GSE 2N4923 3 MOTA 2N5681 3 GSE BC639 3 PHIN D42T1 3 GESY DE128 3 DGE MJE182 3 NSC SD339 3 MIKG	BC311 2N4314 1 RCA 2N3868 3 MOTA D41D7 3 GESY DE129 3 DGE THC4314 3 SPR TP4314 3 SPR	BC324 2N5320 1 RCA BC301 1 SGSI 2N699 3 RCA BD139 3 PHIN D40D7 3 GESY DE128 3 DGE	BC335 BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR	BC340-10 2N2219A 1 PHIN GES2219A 3 GESY THC2219A 3 SPR TN2219A 3 NSC TP2219A 3 SPR	BC351 BC178 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR
BC301 2N699 1 RCA BD139 1 PHIN D40D7 1 GESY 2N2219 3 PHIN 2N3053 3 RCA 2N4923 3 MOTA 2N5320 3 RCA DE128 3 DGE MJE182 3 NSC SD339 3 MIKG THC699 3 SPR	BC312 BC639 1 PHIN BF258 1 SGSI D44T1 1 GESY BCX56 3 PHIN BF337 3 PHIN D40V1 3 GESY THBC639 3 SPR	BC325 BC640 1 PHIN BCX53 3 PHIN THBC640 3 SPR	BC336 BC178 1 SGSI BC858A 3 PHIN THBC178 3 SPR	BC341 2N3053A 1 RCA BC141 1 SGSI 2N5320 3 RCA D40D7 3 GESY GES3053 3 GESY	BC352 BC179 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR THBC558 3 SPR
BC302 2N2270 1 RCA BSX59 1 PHIN 2N5321 3 RCA BSX32 3 SGSI D40D4 3 GESY DE128 3 DGE THC2270 3 SPR	BC313 BC303 1 SGSI D40D4 1 GESY 2N4314 3 RCA BD140 3 PHIN D40D4C 3 SPR	BC327 BC297 1 SGSI BCX17 1 PHIN THBC327 1 SPR 2N2905 3 SGSI 2N2906 3 SGSI 2N2907 3 SGSI 2N4403 3 MOTA BC139 3 SGSI BC177 3 SGSI BC556A 3 PHIN BCW68F 3 SIEG BSS80B 3 SIEG BSS80C 3 SIEG D41D7 3 GESY DE129 3 DGE DE159 3 DGE GES3644 3 GESY MPS6533C 3 SPR MPS6534C 3 SPR MPS6535C 3 SPR PN200 3 NSC PN3644-5 3 NSC THC3644 3 SPR THC4289 3 SPR THC4402 3 SPR THC4403 3 SPR TMPT4402 3 SPR TMPT4403 3 SPR TP3644 3 SPR	BC337 BC377 1 SGSI BCX19 1 PHIN THBC337 1 SPR 2N2218A 3 SGSI 2N2222A 3 MOTA 2N4401 3 MOTA 2N4923 3 NSC BC107 3 SGSI BC108 3 SGSI BC378 3 SGSI BC394 3 SGSI BCW66F 3 SIEG BFY56A 3 SGSI BSS79B 3 SIEG BSS79C 3 SIEG DE85 3 DGE DE123AP 3 DGE DE128 3 DGE DE192A 3 DGE DE199 3 DGE DE289A 3 DGE GES3568 3 GESY MPS3704 3 GESY MPS3705 3 GESY PN100 3 NSC PN3568-5 3 NSC PN3642-5 3 NSC THC3404 3 SPR THC3405 3 SPR THC3416 3 SPR THC3417 3 SPR THC3568 3 SPR THC3642 3 SPR THC3704 3 SPR THC3705 3 SPR THC3793 3 SPR THC3794 3 SPR THC4400 3 SPR THC4401 3 SPR THC4424 3 SPR THC4951 3 SPR THC4952 3 SPR THC4953 3 SPR TMPT4401 3 SPR TP3568 3 SPR TP3642 3 SPR	BC342 2N2102 1 RCA BC141 1 SGSI BC639 1 PHIN 2N2297 3 PHIN 2N4239 3 GSE 2N5320 3 RCA BCX56 3 PHIN BCX56-6 3 SIEG BCX56-10 3 SIEG BFY55 3 PHIN D40D7 3 GESY D40D10 3 GESY DE128 3 DGE THBC639 3 SPR THC2102 3 SPR	BC353 2N4036 1 RCA BC161 1 SGSI BC640 1 PHIN 2N5322 3 RCA BCX53 3 PHIN BCX53-6 3 SIEG BCX53-10 3 SIEG D41D7 3 GESY DE129 3 DGE THBC640 3 SPR THC4036 3 SPR TN4036 3 NSC
BC303 2N4314 1 RCA BD140 1 PHIN 2N3868 3 MOTA 2N4036 3 RCA 2N4920 3 MOTA BC640 3 PHIN D40D4 3 GESY D41D7 3 GESY DE129 3 DGE MJE172 3 NSC SD340 3 MIKG THC4314 3 SPR TP4314 3 SPR	BC314 BC177 1 SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR	BC328-16 THBC327-16 1 SPR BC179 3 SGSI DE290 3 DGE PN200 3 NSC THC4290 3 SPR THC4291 3 SPR	BC338 BC298 1 SGSI BCX18 1 PHIN THBC328 1 SPR BC177 3 SGSI BC178 3 SGSI BC179 3 SGSI BCW67A 3 SIEG	BC343 2N4036 1 RCA BC161 1 SGSI BC640 1 PHIN 2N5322 3 RCA BCX53 3 PHIN BCX53-6 3 SIEG BCX53-10 3 SIEG D41D7 3 GESY DE129 3 DGE THBC640 3 SPR THC4036 3 SPR TN4036 3 NSC	BC354 BC478 1 SGSI BC558 1 PHIN BC557 3 PHIN BC858A 3 PHIN THBC558 3 SPR
BC304 2N4037 1 RCA BC640 1 PHIN BCX52-10 3 SIEG BCX53 3 PHIN BD138 3 PHIN D41D4 3 GESY DE129 3 DGE THBC640 3 SPR THC4037 3 SPR TN4037 3 NSC	BC315 BC177 1 SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR	BC327-25 THBC327-25 1 SPR	BC339 BC298 1 SGSI BCX18 1 PHIN THBC328 1 SPR BC177 3 SGSI BC178 3 SGSI BC179 3 SGSI BCW67A 3 SIEG	BC344 2N2405 1 RCA BC300 1 SGSI BC639 1 PHIN 2N1893 3 RCA 2N2987 3 GSE BCX56 3 PHIN BD139 3 PHIN D42T1 3 GESY THBC639 3 SPR	BC355 BC478 1 SGSI BC558 1 PHIN BC557 3 PHIN BC858A 3 PHIN THBC558 3 SPR
BC307 BC177 1 SGSI SC307 1 MIKG THBC307 1 SPR BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR	BC316 BC107 1 SGSI BC547 1 PHIN THBC318 1 SPR THBC108 3 SPR THBC548 3 SPR	BC328-25 THBC328-16 1 SPR THBC328-25 1 SPR	BC340 BC378 1 SGSI BCX20 1 PHIN THBC338 1 SPR 2N830 3 MOTA BC108 3 SGSI BC109 3 SGSI BCW65A 3 SIEG DE85 3 DGE DE192A 3 DGE DE289A 3 DGE MPS3706 3 GESY PN100 3 NSC THC3402 3 SPR THC3403 3 SPR THC3414 3 SPR THC3415 3 SPR THC3706 3 SPR THC4954 3 SPR	BC345 2N4036 1 RCA BC303 1 SGSI BC640 1 PHIN 2N4314 3 RCA BCX53 3 PHIN BCX53-6 3 SIEG BCX53-10 3 SIEG BD140 3 PHIN D41D7 3 GESY DE129 3 DGE THBC640 3 SPR THC4036 3 SPR TN4036 3 NSC	BC356 BC109 1 SGSI BC548 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR
BC307A THBC307A 1 SPR	BC317 BC107 1 SGSI BC547 1 PHIN THBC317 1 SPR	BC329 BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	BC341 BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	BC346 2N2405 1 RCA BC300 1 SGSI BC639 1 PHIN 2N1893 3 RCA 2N2987 3 GSE BCX56 3 PHIN BD139 3 PHIN D42T1 3 GESY THBC639 3 SPR	BC357 BC479 1 SGSI BC559 1 PHIN BC557 3 PHIN BC859A 3 PHIN
BC307B THBC307B 1 SPR	BC318 BC108 1 SGSI BC548 1 PHIN THBC318 1 SPR THBC108 3 SPR THBC548 3 SPR	BC330 BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	BC342 TP3568 3 SPR TP3642 3 SPR	BC347 BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	BC358 BC109 1 SGSI BC548 1 PHIN BC108 3 SGSI BCF32 3 PHIN THBC109 3 SPR THBC548 3 SPR
BC308 BC178 1 SGSI SC308 1 MIKG THBC308 1 SPR BC858A 3 PHIN THBC178 3 SPR	BC319 BC109 1 SGSI BC549 1 PHIN THBC319 1 SPR BCF32 3 PHIN THBC109 3 SPR	BC331 BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	BC343 THC3416 3 SPR THC3417 3 SPR THC3568 3 SPR THC3642 3 SPR THC3704 3 SPR THC3705 3 SPR THC3793 3 SPR THC3794 3 SPR THC4400 3 SPR THC4401 3 SPR THC4424 3 SPR THC4951 3 SPR THC4952 3 SPR THC4953 3 SPR TMPT4401 3 SPR TP3568 3 SPR TP3642 3 SPR	BC348 BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	BC359 BC179 1 SGSI BC559 1 PHIN BC478 3 SGSI BC859A 3 PHIN THBC179 3 SPR
BC308A THBC308A 1 SPR	BC320 BC177 1 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR	BC332 BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	BC344 2N3053 1 RCA BC140 1 SGSI 2N5321 3 RCA BCX55-10 3 SIEG BSS79C 3 SIEG D40D4 3 GESY	BC349 BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR	BC360-6 2N2904 1 PHIN DE129 3 DGE THC2904 3 SPR TN2904 3 NSC TP2904 3 SPR
BC308B THBC308B 1 SPR	BC321 BC178 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR	BC333 BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	BC345 2N3053 1 RCA BC140 1 SGSI 2N5321 3 RCA BCX55-10 3 SIEG BSS79C 3 SIEG D40D4 3 GESY	BC360-10 2N2905 1 PHIN DE129 3 DGE THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR	BC361 2N4036 1 RCA BC161 1 SGSI 2N5322 3 RCA BCX53-6 3 SIEG BCX53-10 3 SIEG D41D7 3 GESY DE129 3 DGE THC4036 3 SPR THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR
BC308C THBC308C 1 SPR	BC322 BC179 1 SGSI BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR	BC334 BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	BC346 2N3053 1 RCA BC140 1 SGSI 2N5321 3 RCA BCX55-10 3 SIEG BSS79C 3 SIEG D40D4 3 GESY	BC361-10 2N2905 1 PHIN DE129 3 DGE THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR	BC362 BC440 1 SGSI BC868 1 PHIN THBC368 1 SPR BC635 3 PHIN
BC309 BC179 1 SGSI SC309 1 MIKG THBC309 1 SPR BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR	BC323 BC178 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR	BC335 BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	BC347 2N3053 1 RCA BC140 1 SGSI 2N5321 3 RCA BCX55-10 3 SIEG BSS79C 3 SIEG D40D4 3 GESY	BC363 BC460 1 SGSI BC869 1 PHIN THBC369 1 SPR 2N5323 3 RCA	BC363 BC440 1 SGSI BC868 1 PHIN THBC368 1 SPR BC635 3 PHIN
BC309B THBC309B 1 SPR	BC324 BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR	BC336 BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	BC348 BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	BC364 BC298 1 SGSI BC328 1 PHIN BC329 1 PHIN BC330 1 PHIN BC331 1 PHIN BC332 1 PHIN BC333 1 PHIN BC334 1 PHIN BC335 1 PHIN BC336 1 PHIN BC337 1 PHIN BC338 1 PHIN BC339 1 PHIN BC340 1 PHIN BC341 1 PHIN BC342 1 PHIN BC343 1 PHIN BC344 1 PHIN BC345 1 PHIN BC346 1 PHIN BC347 1 PHIN BC348 1 PHIN BC349 1 PHIN BC350 1 PHIN BC351 1 PHIN BC352 1 PHIN BC353 1 PHIN BC354 1 PHIN BC355 1 PHIN BC356 1 PHIN BC357 1 PHIN BC358 1 PHIN BC359 1 PHIN BC360 1 PHIN BC361 1 PHIN BC362 1 PHIN BC363 1 PHIN BC364 1 PHIN BC365 1 PHIN BC366 1 PHIN BC367 1 PHIN BC368 1 PHIN BC369 1 PHIN BC370 1 PHIN	BC365 BC479 1 SGSI BC559 1 PHIN BC557 3 PHIN BC859A 3 PHIN